

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722
Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

13/01/2022

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1

Veh # :- SLD1922U

Veh Model :- TOYOTA CAMRY

Estimate# :- CK422756

Claim # :- TP/CK14346

ACC. Date :- 07/01/22

Terms :- C.O.D Days

Remarks :- WFF 02 JAN 2021 (2019)

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	HEADLAMP LH	1 PC	2,719.00	2,719.00 X
2.	HEADLAMP LOWER MOULDING LH	1 PC CM	223.00	223.00 ✓
3.	FRONT BUMPER	1 PC	625.00	625.00 ✓
4.	FOG LAMP COVER LH	1 PC	161.00	161.00 X
5.	FRONT BUMPER LOWER LID LH	1 PC	228.00	228.00 X
6.	FRONT BUMPER CLIPS	10 PC	5.00	50.00 ✓
7.	FRONT BUMPER SIDE RETAINER LH	1 PC	95.00	95.00 X
LIST TOTAL S\$				4,101.00
25% DISCOUNT S\$				-1,025.25
				3,075.75
LABOUR :				
TO INSPECT FRONT LIGHTING MECHANISM & CHECK WIRING.				80.00
TO REMOVE & REPLACE DAMAGED ITEMS, TO REMOVE TRANSFER AFFECTED ATTACHMENT. REALIGN CONNECTION				280.00
TO SPRAY PAINT ON REPAIRED AREAS				280.00
LABOUR TOTAL S\$				640.00

Not Authorized
Resurvey B6 part

E. & O.E

2 days

NON-TAX AMOUNT S

AMOUNT S\$ 3,715.75

GST @ 7 % 260.10

AMOUNT DUE S\$ 3,975.85

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation

- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed

- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

MOVA AUTOMOTIVE PTE LTD

Jacelyn