

(08/11/13) wef

ASS. REC. BY: Marcus

REF:

CS/SMD 22000622/urf3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No. CMTD2200193/AGC

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date:

Person Contacted:

Rep 17/11/22 STA 31990

Veh No:

SKS 6259B

Yr Regn:

28/4/15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

made S

c.c

1998

Colour:

Red

A/C: Insured / Std / NI / NA

Sp. Reading:

111526

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

JM6CW1071F0121341

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

offered

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

205/55-R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Kapsen

Front

6

Rear

6

R/Bal.

mm

R/Bal.

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

12/1/22

D.O.I.

18/1/22

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

2/5 Frt, 0/5 Body & N/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

ENY 1-2-22 vehicle went up kerb
tailay o/s cracked sol 3 yrs 3mth
Rear system o/s car

offer Billy not more than 1/10

18/4/22 vehicle claims o/d already submit

18/4/22

Submit preli report-revised fig \$14,628.40 check items \$4351.20

Date/Time, File Pass to?



Preli. Report

1)



Final Report

Date/Time, File Return to?

2) 18/4/22-typist

Days Of Repair: 10

Resurvey No. of Trip:

Survey Fee:

Transportation:

Report Format :

Lump Sum / I.B.I: (\$)

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

) S + RS, SI

) Photos

) Others

)

TOTAL

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC

Owner ID: 872G

Vehicle Details

Vehicle No.: SKS6259B

Vehicle to be Exported: No

Intended Deregistration Date: 14 Jan 2022

Vehicle Make: MAZDA

Vehicle Model: MAZDA5 5-DOOR WAGON 2.0L SP.6EAT SUNROOF

Primary Colour: Red

Manufacturing Year: 2015

Engine No.: PE10215013

Chassis No.: JM6CW1071F0121341

Maximum Power Output: 111.0 kW (148 bhp)

Open Market Value: \$17,873.00

Original Registration Date: 28 Apr 2015

First Registration Date: 28 Apr 2015

Transfer Count: 1

Actual ARF Paid: \$12,873.00 6436

Intended PARF Rebate Details

PARF Eligibility: Yes

PARF Eligibility Expiry Date: 27 Apr 2025

PARF Rebate Amount: \$8,367.00

Intended COE Rebate Details

COE Expiry Date: 27 Apr 2025

COE Category: E - Open Category

COE Period(Years): 10

QP Paid: \$72,100.00

COE Rebate Amount: \$23,623.00

Total Rebate Amount: \$31,990.00

The information contained herein is correct as at 14 Jan 2022

OK

SGCARMART.COM

Login Sign up

New Cars Used Cars Rental Cars Sell My Car Directory Products Insurance Articles Forum Resources



Mazda 5

Price Range



Depreciation



2015



Vehicle Type



Search

Advanced Search


Used Car Comparison

--- Comparing 3 Vehicles ---

Mazda 5 2.0A Sunroof

Mazda 5 2.0A Sunroof

Mazda 5 2.0A Sunroof



Clear All

Add all to Shortlist

Back to search result

Add to Shortlist

Add to Shortlist

Add to Shortlist

Use search bar above to search to compare.

CAR DETAILS

Price	\$44,000	\$48,737	\$45,500
Instalment	\$834	\$923	\$904
Registration Date	28-May-2015	22-May-2015	17-Mar-2015
Manufactured	2015	2015	2015
Mileage	141,000 km	82,000 km	-
Transmission	Auto	Auto	Auto
Engine Cap	1,998 cc	1,998 cc	1,998 cc
Road Tax	\$1,210 /yr	\$1,210 /yr	\$1,210 /yr
Power	111.0 kW (148 bhp)	111.0 kW (148 bhp)	111.0 kW (148 bhp)
Curb Weight	1,535 kg	1,535 kg	1,535 kg
Features	2.0L 16V DOHC Engine, Motorised Passenger Doors, Sunroof, Airbags, Etc.	Inline 4 Cylinders Sky-Activ NA Engine, Sliding Doors, Most MEconomic And Compact 7 Seaters, Pioneer HU, Multi Functional Steering, Auto Headlamp.	-
Accessories	-	New Chilli Red Paintwork, New Rims, New Tyres, New Carpet, New Pioneer HU, New Visors/Sunshade. Full Servicing All Done. New Rd Tax. Call For Viewing.	-
Description	THE ONLY 2.0L MPV AT THIS PRICE! Reliable, Spacious, Good Looking And More Affordable Than Your Wife's Handbag! The Car Drives Beautifully, Come See For Yourself! PRICED TO SELL! Consignment Unit, Viewing Is Strictly By Appointment. Multiple Loan Options Available.	2 Digit Bidded Number Plate Goes Along, Regardless Of Condition Or Price, Excellent Conditions Assured! Highest Trade In Available For All, 100% Loan Approval. Absolutely No Repairs Needed. STA/VICOM Reports, Any Workshop Inspection All Are Welcome. All Bank/Finance/In House Loan Are Available, Lowest Interest Rates. Price Negotiable, Viewing By Appointment Only, Everyday From 3pm Onwards	3/15 Mazda 5. 5 Doors Wagon 2.0 With Sunroof. 6 Seaters, 1 Transfer. Silver Colour. OMV \$17,946.
COE	\$78,004	\$77,600	\$68,668
OMV	\$17,538	\$17,665	\$17,946
ARF	\$12,538	\$12,665	\$12,946
Depreciation	\$11,210 /yr	\$12,660 /yr	\$12,310 /yr
No. of Owners	3	2	2
Type of Vehicle	MPV	MPV	MPV
Category	PARF Car, Premium Ad Car	PARF Car, Consignment Car	PARF Car, Premium Ad Car
Availability	Available	Available	Available

SELLER INFORMATION

Seller

not Authorised
new
new
90096608
limited Repair



Main Office:
Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:
Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314
Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

17/01/2022

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1
Veh # :- SKS6259B
Veh Model :- MAZDA 5
Estimate# :- CK422773
Claim # :-
ACC. Date :- 12/01/22
Terms :- C.O.D Days
Remarks :-

10 day?
18/1/22

No.	Description	Qty	U.Price	Amounts S\$
LIST ITEMS :				
1.	FRONT WINDSCREEN GLASS MOULDING	1 PC	68.00	68.00
2.	HEADLAMP ASSY RH - CHECK	1 PC		X
3.	FRONT BUMPER (REPAIR)	1 PC		X
4.	FRONT BUMPER RETAINER RH	1 PC	22.00	22.00 X
5.	FRONT BUMPER CLIPS	10 PC	5.00	50.00 ✓
6.	SUPPORT PANEL - CHECK	1 PC		X
7.	FRONT FENDER RH	1 PC	323.00	323.00 ✓
8.	FRONT FENDER INNER PANEL RH	1 PC	1,184.00	1,184.00 X
9.	FRONT FENDER COWLING RH	1 PC	221.00	221.00 ✓
10.	FRONT FENDER COWLING CLIPS	10 PC	5.00	50.00 ✓
11.	FRONT SPORT RIM RH & LH	2 PC	1,156.00	2,312.00 s/v
12.	FRONT KNUCKLE BEARING RH & LH	2 PC	168.00	336.00 ?
13.	FRONT KNUCKLE HUB RH & LH	2 PC	154.00	308.00 ?
14.	FRONT KNUCKLE ARM RH & LH	2 PC	395.00	790.00 ?
15.	FRONT SHOCK ABSORBER RH & LH	2 PC	266.00	532.00 ?
16.	FRONT SHOCK ABSORBER TOP MOUNTING RH & LH	2 PC	153.00	306.00 X
17.	FRONT LOWER ARM RH & LH	2 PC	411.00	822.00 ?
18.	FRONT CROSS MEMBER - CHECK	1 PC		?
19.	ENGINE UNDER COVER	1 PC	359.00	359.00 ?
20.	STERRING RACK & PINION - CHECK	1 PC		?
21.	FRONT DRIVER SEAT RH - CHECK	1 PC		?
22.	FRONT STABILIZER BAR - CHECK	1 PC		?
23.	FRONT STABILIZER BAR LINKAGE	1 PC	98.00	98.00 ?
24.	FRONT DOOR PILLAR RH	1 PC	1,030.00	1,030.00 ✓
25.	FRONT DOOR PILLAR GARNISH RH	1 PC	58.00	58.00 ?
26.	FRONT DOOR RH	1 PC	1,205.00	1,205.00 ✓
27.	FRONT DOOR MIRROR RH	1 PC	379.00	379.00 ✓
28.	FRONT DOOR MIRROR COVER RH	1 PC	100.00	100.00 ✓
29.	FRONT DOOR MIRROR SIGNAL RH	1 PC	289.00	289.00 ✓
30.	FRONT DOOR HINGE TOP RH	1 PC	45.00	45.00 ✓
31.	FRONT DOOR CHECKER RH	1 PC	66.00	66.00 ✓
32.	FRONT DOOR HINGE BOTTOM RH	1 PC	47.00	47.00 ✓
33.	FRONT DOOR STICKER RH	1 SET	124.00	124.00 ✓
34.	FRONT DOOR OUTER MOULDING RH	1 PC	44.00	44.00 ✓
35.	FRONT DOOR OUTER HANDLE RH	1 PC	145.00	145.00 ✓
36.	FRONT DOOR LOCK RH	1 PC	468.00	468.00 ✓
37.	FRONT DOOR WEATHERSRTIP RH	1 PC	81.00	81.00 ✓
38.	FRONT DOOR GLASS REGULATOR RH	1 PC	156.00	156.00 ?
39.	FRONT DOOR GLASS REGULATOR MOTOR RH	1 PC	321.00	321.00 ?
40.	FRONT DOOR OUTER HANDLE NOB RH	1 PC	42.00	42.00 ✓
41.	FRT DOOR OUTER HANDLE INNER BRACKET RH -CHECK	1 PC		?
42.	FRONT DOOR INNER TRIM RH - CHECK	1 PC		?
43.	ROCKER PANEL GARNISH RH & LH	2 PC	1,109.00	2,218.00 X
44.	CENTER PILLAR RH (REPAIR)	1 PC		?
45.	REAR DOOR RH	1 PC	1,405.00	1,405.00 ✓
46.	REAR DOOR STICEKR RH	1 SET	60.00	60.00 ✓
47.	REAR DOOR OUTER HANDLE RH	1 PC	137.00	137.00 ✓
48.	REAR DOOR OUTER HANDLE NOB RH	1 PC	58.00	58.00 ✓
49.	REAR DOOR WEATHERSTRIP RH	1 PC	148.00	148.00 X
50.	REAR DOOR LOCK RH - CHECK	1 PC		X
51.	REAR DOOR GLASS REGULATOR RH - CHECK	1 PC		?

Estimate

17/01/2022

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1 143656

Veh # :- SKS6259B

Veh Model :- MAZDA 5

Estimate# :- CK422773

Claim # :-

ACC. Date :- 12/01/22

Terms :- C.O.D Days

Remarks :-

Main Office:
 Mova Building
 No. 22, Jalan Kilang,
 Singapore 159419
 Tel: (65) 6476 3333
 Fax: (65) 6271 5891
 www.mova.com.sg

Workshop Dept:
 Block 1008,
 Bukit Merah Lane 3,
 #01-04/06/08/94
 Singapore 159722
 Tel: (65) 6272 3892
 Fax: (65) 6270 8314
 Co. Reg. 198904033G
 GST Reg. M2-0088864-2

No.	Description	Qty	U.Price	Amounts S\$
52.	REAR DOOR GLASS REGULATOR MOTOR RH - CHECK ?	1 PC		?
53.	REAR QUATER GLASS MOULDING RH	1 PC	105.00	105.00 ✓
54.	REAR FENDER RH <i>Body</i>	1 PC	2,428.00	2,428.00 ✓
55.	REAR BUMPER <i>Body</i>	1 1	962.00	962.00 ✓
56.	REAR BUMPER RETAINER RH <i>Body</i>	1 PC	48.00	48.00 ✓
57.	REAR BUMPER CLIPS <i>Body</i>	10 PC	5.00	50.00 ✓
	LIST TOTAL S\$			20,000.00
	20% DISCOUNT S\$			-4,000.00
				16,000.00
	SPECIAL NET ITEMS :			
1.	FRONT WINDSCREEN GLASS SEALANT <i>net</i>	1 PC	40.00	40.00 ✓
2.	FRONT TYRE RH <i>net</i>	1 PC	250.00	250.00 ✓
3.	REAR QUATER GLASS SEALANT RH <i>net</i>	1 PC	40.00	40.00 ✓
	SPECIAL NET TOTAL S\$			330.00
	LABOUR :			
	TO CUT / WELD FRONT DOOR PILLAR RH, CENTER PILLAR RH, FRONT FENDER INNER PANEL RH, REAR FENDER RH. KNOCK & STRAIGHTEN FRONT & REAR BODY MEMBER, REMOVE & REPLACE ACCIDENT DAMAGED PARTS. REALIGN ALL CONNECTION		1400	1,600.00
	TO SPRAY PAINT FRONT BUMPER, FRONT FENDER RH, FRONT FENDER INNER PANEL RH, FRONT DOOR PILLAR RH, FRONT DOOR MIRROR RH, FRONT DOOR RH, ROCKER GARNISH RH & LH, CENTER PILLAR RH, REAR DOOR RH, REAR FENDER RH, REAR BUMPER		1600	1,800.00
	REMOVE & REPLACE A/C CONDERSER, PIPE, HOSE & RECHARGE A/C GAS		111X	120.00
	REMOVE & REPLACE FRONT WINDSCREEN GLASS & CHECK WATER LEAKAGE		✓	120.00
	REMOVE & REPLACE DASHBOARD ASSY, GLOVE BOX & OTHER ATTACHMENT PARTS		✓	250.00
	REMOVE & REPLACE FRONT DOOR INNER TRIM, MECHANISM & CHECK LOCKING SYSTEM		✓	50.00
	REMOVE & REPLACE DOOR INNER TRIM, MECHANISM & CHECK LOCKING SYSTEM		✓	50.00
	REMOVE & REPLACE FRONT & REAR SEAT, UPHOSTERY SIDE GARNISH, COVERING		80	160.00
	REMOVE & REPLACE REAR QUATER GLASS & CHECK			

Main Office:

Mova Building
No. 22, Jalan Kilang,
Singapore 159419
Tel: (65) 6476 3333
Fax: (65) 6271 5891
www.mova.com.sg

Workshop Dept:

Block 1008,
Bukit Merah Lane 3,
#01-04/06/08/94
Singapore 159722

Tel: (65) 6272 3892
Fax: (65) 6270 8314

Co. Reg. 198904033G
GST Reg. M2-0088864-2

Estimate

17/01/2022

SOMPO INSURANCE SINGAPORE PTE LTD
50 RAFFLES PLACE
#05-01/06 SINGAPORE LAND TOWER
SINGAPORE 048623.

Attention :- XA018

Page # :- 1 143656

Veh # :- SKS6259B

Veh Model :- MAZDA 5

Estimate# :- CK422773

Claim # :-

ACC. Date :- 12/01/22

Terms :- C.O.D Days

Remarks :-

No.	Description	Qty	U.Price	Amounts S\$
	WATER LEAKAGE		11	100.00 X
	REMOVE & REPLACE FRONT UNDER CARRIAGE SUSPENSION, FRONT CROSS MEMBER		350?	380.00
	TO CHECK CHASSIS ALIGNMENT ON LASER LOCK MACHINE		11 X	280.00
	TO APPLY SEAL ON WELDING JOINTS			100.00 ✓
	COMPUTER WHEEL ALIGNMENT			60.00 ✓
	RUST PROOF AFFECTED AREAS		120	150.00
	LABOUR TOTAL S\$			5,220.00

E. & O.E

NON-TAX AMOUNT S

AMOUNT S\$ 21,550.00

GST @ 7 % 1,508.50

AMOUNT DUE S\$ 23,058.50

Customer's Signature/Co. Stamp MOVA AUTOMOTIVE PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: