



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925
	Document No. 0	
	Document Date 18/01/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZVW40R	AWXEBW Q3	23/02/2021	SMY1960L	0	12811	75/DS/SMY1960L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU10J059924	2ZR2F74130	60	Ng Mei Yen	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:GBG3995Z ACC DATE:17/01/2022 TOW IN:17/01/2022 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00
2	B	BP-LAB2 CHECK WIRING & CONDUCT LEAK TEST				180.00
3	S	BP-SUBLET RESET ECU UPON COMPLETION OF REPAIR				180.00
4	B	BP-LAB2 DRILL HOLE & INSTALL REVERSE SENSOR				180.00
5	B	BP-LAB2 TRANSFER TAILGATE MACH				720.00
6	B	BP-LAB2 REPL ACC AFF AREA STRAIGHTEN & PANEL BEAT ACC AFF AREA				5040.00
7	B	BP-RES2 RESPRAY ACC AFF AREA				4130.00
8	Z	BP-BKT SUPPLY PHV STICKER				20.00
9	L	BP-LPO SUPPLY FRONT REGN PLATE (PO#)				80.00
10	1	U52119-47969 COVER, FR BUMPER	1.00	589.50	25.00	442.12
11	2	U53102-47180 GRILLE SUB-ASSY,	1.00	597.00	25.00	447.75
12	3	U52611-47100 ABSORBER, FR BUMPER	1.00	84.20	25.00	63.15
13	4	U52021-47160 REINFORCEMENT	1.00	696.00	25.00	522.00
14	5	U53111-47110 GRILLE, RADIATOR	1.00	510.10	25.00	382.57

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details	Account No.	Customer Details
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925
	Document No. 0	
	Document Date 18/01/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZVW40R	AWXEBW Q3	23/02/2021	SMY1960L	0	12811	75/DS/SMY1960L

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDZS3EU10J059924	2ZR2F74130	60	Ng Mei Yen	--/--/----	0.00 --/--/---- 0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
15	6	U81140-47660 UNIT ASSY, HEADLAMP,	1.00	2678.10	25.00	2008.57
16	7	U81070-47660 UNIT ASSY, HEADLAMP,	1.00	2678.10	25.00	2008.57
17	8	U81210-47010 LAMP ASSY, FOG, RH	1.00	329.00	25.00	246.75
18	9	U81220-47010 LAMP ASSY, FOG, LH	1.00	313.00	25.00	234.75
19	0	U52159-47912 COVER, RR BUMPER	1.00	589.50	25.00	442.12
20	1	U52155-47010 SUPPORT, RR BUMPER	1.00	151.20	25.00	113.40
21	2	U52156-47010 SUPPORT, RR BUMPER	1.00	151.20	25.00	113.40
22	3	U52591-47030 SEAL, RR BUMPER	1.00	95.40	25.00	71.55
23	4	U52592-47030 SEAL, RR BUMPER	1.00	136.80	25.00	102.60
24	5	U52023-12240 REINFORCEMENT	1.00	230.20	25.00	172.65
25	6	U58307-47080 PANEL SUB-ASSY, BODY	1.00	738.00	25.00	553.50
26	7	U61602-47131 PANEL SUB-ASSY,	1.00	1023.30	25.00	767.47
27	8	U58742-47020 PROTECTOR, QUARTER	1.00	24.40	25.00	18.30
28	9	U67005-47460 PANEL SUB-ASSY, BACK	1.00	1177.30	25.00	882.97
29	0	U67881-47040 WEATHERSTRIP, BACK	1.00	355.10	25.00	266.32
30	1	U68105-47190 GLASS SUB-ASSY, BACK	1.00	1093.60	25.00	820.20
31	2	U56117-50140 DAM, WINDOW GLASS	1.00	30.60	25.00	22.95
32	3	U67750-47050 CO BOARD ASSY, BACK	1.00	348.70	25.00	261.52
33	4	U81551-47262 LENS & BODY, RR	1.00	730.90	25.00	548.17
34	5	U81561-47252 LENS & BODY, RR	1.00	706.10	25.00	529.57

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others	Less Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



ESTIMATE

Account Details	Account No.	Customer Details
MSIG Insurance (Singapore) Pte Ltd 4 Shenton Way #21-01 SGX Centre 2 Singapore 068807 Attn: Motor Claims Dept	S1000037 / ICCUA2	M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925
	Document No. 0	
	Document Date 18/01/2022	

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2020	ZVW40R	AWXEBW Q3	23/02/2021	SMY1960L	0	12811	75/DS/SMY1960L
Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On		
JTDZS3EU10J059924	2ZR2F74130	60	Ng Mei Yen	--/--/----	0.00	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
35	6	U81910-47010 REFLECTOR ASSY,	1.00	63.40	25.00	47.55
36	7	U81920-47010 REFLECTOR ASSY,	1.00	63.40	25.00	47.55
37	8	U76891-47040 SPOILER, RR NO.1	1.00	899.70	25.00	674.77
38	9	U76801-47140 E2 GARNISH SUB-ASSY,	1.00	459.60	25.00	344.70
39	0	U75310-33050 EMBLEM ASSY,	1.00	112.30	25.00	84.22
40	1	U75442-47080 PLATE, BACK DOOR	1.00	67.20	25.00	50.40
41	2	U75310-47020 EMBLEM ASSY,	1.00	67.20	25.00	50.40
42	3	U75441-47130 PLATE, LUGGAGE COMPT	1.00	58.00	25.00	43.50
43	4	U75374-47112 EMBLEM, SIDE PANEL	1.00	58.00	25.00	43.50
44	5	TREVSE-47006 4X1 BACK SENSOR STEEL BLONDE ME	1.00	101.05		101.05

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd	Please acknowledge receipt of vehicle		24,160.56
		Parts 13,530.56	GST 7.00% 1,691.24
		Labour 10,370.00	
		Sublet 260.00	Less 0.00
		Lubrication/Fluid 0.00	
		Others 0.00	Amount Due 25,851.80

Customer Copy