



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
HSBC LIFE (SINGAPORE) PTE LTD 10 MARINA BOULEVARD #48-01 MARINA BAY FINANCIAL CENTRE TOWER 2 SINGAPORE 018983 ATTN: TEO KITTY		Ref: CS/ASM22000643/Tny3m4 Date: 23/02/2023 Code: HSB	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SJA 9980M	Veh. Inspected	SJR 7722R
Policy No.	GA483278	Coverage (\$)	0.00
Claim No.	S2M03QWL	Excess (\$)	0.00
Assign From	TEO KITTY	Assign Date	18/01/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA VEZEL HYBRID	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	RU31118557	Colour	BLUE
Odometer	227250 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/60 R16	PIRELLI	6 mm
L/H Front Tyre	215/60 R16	PIRELLI	6 mm
R/H Rear Tyre	215/60 R16	PIRELLI	6 mm
L/H Rear Tyre	215/60 R16	PIRELLI	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION AND UNDERCARRIAGE. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	11/01/2022	Inspection Date	20/01/2022
Survey held at	1 KAKI BUKIT AVENUE 6 #01-08 AUTOBAY@KAKI BUKIT		
Repairer	TSL AUTO GARAGE		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	