

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT						
	AXA INSURANCE	PTE LTD	F	Ref:	CS3/ASM22000650/Tvy3e2	
	8 SHENTON WAY SINGAPORE 0688	[Date:	11/02/2022		
	ATTN: KHONG LYI	NN	(Code:	ASM	
1.	Policy Particulars :- (THIRD PARTY CLAIM)					
	Insured Veh.	SFW 456B	Veh. Inspected		PC 3110R	
	Policy No.	GA567007	Coverage (\$)		0.00	
	Claim No.	S2M03R7U	Excess (\$)		0.00	
	Assign From	KHONG LYNN	Assign Date		18/01/2022	
2.	Vehicle Particulars & Condition					
	Make & Model	TOYOTA HIACE COMMUTER	c.c		2982	
	Engine No.	HIDDEN	Year of Reg.		2014	
	Chassis No.	KDH2230021514	Colour		WHITE	
	Odometer	410676 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		NIL	
	General	GOOD				
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre	195 R15	BRIDGESTONE		6 mm	
	L/H Front Tyre	195 R15	BRIDGESTONE		6 mm	
	R/H Rear Tyre	195 R15	BRIDGESTONE		6 mm	
	L/H Rear Tyre	195 R15	BRIDGESTONE		6 mm	
4.	Description of Damages					
	THE VEHICLE SUS	HICLE SUSTAINED DAMAGES AT THE REAR PORTION.				
5.	General Information					
	Accident Date	14/01/2022	Inspect Date / Ti	ime	21/01/2022 (11:35 AM)	
	Survey held at	KAKI BUKIT #07-38 SYNERGY				
	Repairer	Repairer PIERRE@XCLUSIVE MOTORS PTE LTD				
5a.	Remarks					
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$5,000-\$6,000					
5b.	Estimate Days of Repair					
	ESTIMATED NORMAL PERIOD FOR REPAIR: 7 Working Days					

Report Ref No. CS3/ASM22000650/Tvy3e2

Inspected By

MOHAMAD TAUFIKH M.MATAI, AMSAE-A

K.K.LAU CPT(RET)

 $BEng(Hons), B. Bus, MBA, PEng, PE, \, MInstAEA, MASME, MIRTE$

REGD Auto Consultant-SAE, Licensed Appraiser

Automotive Assessor DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.