

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.
3 Anson Road
#16-00 Springleaf Tower
Singapore 079909

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Pauline Tham

Date: 20 Jan 2022

Preliminary Advice

Vehicle No	: SMA6329D	Accident Date	: 04/01/2022
Make	: TOYOTA VIOS	Policy No.	: DMPCSNA00101132102
Assignment Date	: 18/01/2022	Excess	: S\$0.00
Date of Inspection	: 19/1/2022	Est. Duration of Repair	: 14
Inspection At	: CAR CITY AUTO CENTRE PTE LTD		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	40,152.80
Revised Amount	:S\$	23,215.80
Check Items (Estimated)	:S\$	14,292.00
Total	:S\$	37,507.80
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	66,800.00
COE / PARF Rebate	:S\$	36,052.00
Salvage Value	:S\$	
Margin for Repair	:S\$	30,748.00

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- (X) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments :Repairer unable to undertake the repair within the Nett Value.