

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (MOTORRAD)

Sunny and repair
18.01.2022



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 60642
Date Estimated : 17/01/2022
Prepared By : Foong Shiuh Jye

Page No. : 1 of 6

- ESTIMATE REPAIR FOR -

Vincent Chiun Tze Yen
109 Pasir Ris Street 11
#05-601

Singapore 510109

- ACCOUNT - 137

Allianz Global Corporate & Specialty SE
Singapore Branch
12 Marina View
Singapore 018961
#14-01 Asia Square Tower 2

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFR111Y	WBATR12060LS31082	26/11/2019	X3 sDrive20i	35839

DESCRIPTION

To replace front bumper, front bonnet, front attachments, rear bumper, tailgate and tail end panel

3400 / 7,650.00

To spray paint bumper front panel, bonnet, tailgate, bumper rear panel and tailend panel

4191 / 5,155.00

To carry out body cavity preservation.
(Per panel).

112 / 236.00

To supply front emboss number plate.

(vt)

83.00

To replace radiator assembly, fan housing with fan including pressure test, bleed cooling system and conduct check for leak. (All models except 7 series).

728

728 / 767.00

To replace charge air cooler including conduct check for leak and proper function.

504

X 531.00

To replace both left and right headlights.

784

457 / 837.00

To replace air con condenser and air con hose including vacuum system, top up freon gas and conduct check for leak. (For all models except for 7 series).

952

X 1,003.00

To replace front or rear PDC sensor wire harness including reset and conduct check for proper function.

252 / 266.00

To check electrical wiring system and lighting including reset and check air bag for proper function.

280 / 295.00

Sundries.

150.00

Total Labour 1: 16,973.00

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Page No. : 2 of 6

Estimate No. : b1 60642
Date Estimated : 17/01/2022
Prepared By : Foong Shih Jye

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFR111Y	WBATR12060LS31082	26/11/2019	X3 sDrive201	35839

DESCRIPTION	QTY	PRIC	VALUE
RADIATOR (FRONT) <i>1 DD</i>	1	779.15	779.15
RADIATOR <i>1 X nn</i>	1	865.70	865.70
TAIL PANEL <i>1 X nn</i>	1	512.50	512.50
TRUNK LID <i>1 X R</i>	1	2,020.65	2,020.65
BONNET <i>1 DD</i>	1	1,901.40	1,901.40
FRT BUMPER FLAP TOWING EYE <i>1 cut</i>	1	41.85	41.85
GRILLE AIR INLET MIDDLE <i>1 X nn</i>	1	92.85	92.85
FRT SHOCK ABSORBER <i>1 BR</i>	1	75.00	75.00
FRT BUMPER TOP CARRIER <i>1 DD</i>	1	847.75	847.75
FRT BUMPER BOTTOM CARRIER <i>1 X nn</i>	1	466.25	466.25
LH VERTICAL STRUT <i>1 X nn</i>	1	51.80	51.80
RH VERTICAL STRUT <i>1 X nn</i>	1	51.80	51.80
FRT UNDERRIDE PROTECTION (X LINE) <i>1 X nn</i>	1	243.85	243.85
LH SIDE GRILLE OPEN WITH PDC (NEBEL) <i>1 X nn</i>	1	92.85	92.85
RH SIDE GRILLE OPEN WITH PDC (NEBEL) <i>1 cut BR</i>	1	92.85	92.85
FRT BUMPER PANEL PRIMED (PMA) <i>1 BR</i>	1	1,427.70	1,427.70
FRT BUMPER COVER (PDC) <i>1 BR X nn</i>	1	713.80	713.80
SET MOUNTING PDC/PMA SENSOR FRT <i>1 X nn</i>	1	68.40	68.40
REAR BUMPER CARRIER <i>1 DD</i>	1	765.35	765.35
LH SIDE GUIDE FOR BUMPER <i>1 X nn</i>	1	134.30	134.30
RH SIDE GUIDE FOR BUMPER <i>1 X nn</i>	1	134.30	134.30
RH BUMPER GUIDE <i>1 X nn</i>	1	161.15	161.15
REAR UNDERRIDE GUARD (X LINE) <i>1 CR4</i>	1	243.85	243.85
REAR BUMPER PANEL PRIMED (X LINE PM) <i>1 CR4</i>	1	1,539.85	1,539.85
REAR BUMPER CLADDING (PDC) <i>1 CR4</i>	1	611.15	611.15
REAR BUMPER TOWING EYE COVER <i>1 CR4</i>	1	48.10	48.10
FRT LH GRILLE (X LINE) <i>1 cut</i>	1	157.10	157.10
FRT RH GRILLE (X LINE) <i>1 cut</i>	1	157.10	157.10
REAR SILENCER HEAT INSULATION <i>1 X nn</i>	1	77.30	77.30
AIR DUCT TOP <i>1 BR</i>	1	221.85	221.85
AIR DUCT BOTTOM <i>1 BR</i>	1	144.45	144.45
AIR DUCT RADIATOR TOP <i>1 BR</i>	1	105.90	105.90
AIR DUCT RADIATOR BOTTOM <i>1 BR</i>	1	105.90	105.90
FRT LH BRAKE AIR DUCT <i>1 BR</i>	1	65.10	65.10
FRT RH BRAKE AIR DUCT <i>1 BR</i>	1	65.10	65.10
LH AIR DUCT BRAKE WHEEL ARCH <i>1 X nn</i>	1	65.10	65.10
RH WHEEL ARCH BRAKE AIR DUCT <i>1 X nn</i>	1	65.10	65.10
AIR FLAP CONTROL ACTIVE TOP <i>1 X nn</i>	1	99.15	99.15
Total Parts :			15,313.35

Performance Motors Limited

A Sime Darby Motors Company
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X
Toll-Free Number (1800-2255269)

303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Fax. 63449773

115, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Fax. 64796601 (AfterSales)
64796624 (Motorrad)



GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 60642
Date Estimated : 17/01/2022
Prepared By : Foong Shiuh Jye

Page No. : 3 of 6

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SFR111Y	WBATR12060LS31082	26/11/2019	X3 sDrive20i	35839

Steve CLKK)
19/1/22, 11.30am

OD-N1 AL
Excess- ?
P/P
My BL 5g
12 ~~12~~ dys

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:



Labour 1	:	16,973.00
Parts	:	15,313.35
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	2,260.04
Grand Total	:	34,546.39

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **