

TP Smpo.
Xiao Chun.
PRS.

SM67187H.

Toyota Vios.

MROS3H9305143798.

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

950

Front Door

Protector

180

Lock.

280

Inner Trim Board.

480

Glass Regulator Gear.

280

Outer Handle.

120

950

Rear Door

Protector

180

Rear Bumper

480

Side Holder

30

Rear Wheel Rim.

500

4430

3322.50

Labour

700

1880

Spry Painting

800

Wiring

30

bl: 520.5

Transfer lock fittings.

160

L/S: A.I.K.

To move rear sensor

50

Tuftcoat

60

Wheel Alignment +

80

Range: HK - 43K
0.5K