

⏪

⏩

1 of 2 ?

⏴

⏵

↺

↻

100% ▾

🖨

📄

Find | Next



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INDIA INTERNATIONAL INSURANCE PL			Ref: CS3/III21011098/R1vf3-1	
64 CECIL STREET			Date: 18/01/2022	
#05-02 IOB BUILDING SINGAPORE 049711			Code: III2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLR 9430X	Veh. Inspected	SMU 5130K	
Policy No.		Coverage (\$)	0.00	
Claim No.	MFL2021D0004633	Excess (\$)	0.00	
Assign From	CARINE KEK PHER SER	Assign Date	18/01/2022	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	21/10/2021	Inspection Date	18/01/2022	
Survey held at	7 SIN MING INDUSTRIAL EST SECTOR C #01-92			
Repairer	V8 MOTOR WERKZ PTE LTD			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				