



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22000664/Uqf3e2	
			Date: 02/03/2022	
			Code: AIS	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SJG 1001K	Veh. Inspected	FBQ 7996S
	Policy No.		Coverage (\$)	0.00
	Claim No.	2021 20003297GK	Excess (\$)	0.00
	Assign From	SHANTI	Assign Date	19/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA ADV150	c.c	149
	Engine No.	HIDDEN	Year of Reg.	2019
	Chassis No.	MH1KF6113KK007706	Colour	RED
	Odometer	50155 KM	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/80-14	PIRELLI	7 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	130/70-13	PIRELLI	7 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S BODY AND FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	17/12/2021	Inspection Date	19/01/2022
	Survey held at	EROFIA MOTOR TRADING PTE LTD 1 KAKI BUKIT AVENUE 6 #02-62 SINGAPORE 417883		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	