



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
CHINA TAIPING INSURANCE (S) PTE LTD 3 ANSON ROAD #16-00 SPRINGLEAF TOWERS SINGAPORE 079909			Ref: CS/CTI22000667/Eqy3n2	
			Date: 05/04/2022	
			Code: CTI	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GBH 3894B	Veh. Inspected	SLT 3776C	
Policy No.	DMCVSNW00054092100	Coverage (\$)	0.00	
Claim No.	SNM22D200414/C02	Excess (\$)	0.00	
Assign From	IRENE TAY	Assign Date	19/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	LAND ROVER DISCOVERY	c.c	2993	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	SALRA2AK8HA038154	Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	15/01/2022	Inspection Date	24/01/2022	
Survey held at	WEARNES AUTOMOTIVE PTE LTD 45 LENG KEE ROAD SINGAPORE 159103.			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				