

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

AXA MSIG Insurance (Singapore) Pte Ltd

No. 4 Shenton Way

0128-01 SOX Centre 2

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0034/2021/JT
DATE : 12-Jan-22
WIP : 63150

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 18/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR SHI YAN
ADDRESS : BLK 41 CHAI CHEE STREET
#09-14
SINGAPORE 461041
TELEPHONE : HP +65 83999708
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900260812-01
VEHICLE NO : **SMR 2559 T**
MODEL CODE : AUDI A1 SB ADVANCED 1.0 TFSI
MODEL YEAR : 26/12/2019
ENGINE NO : DKJ 047166
CHASSIS NO : WAUZZZGB5LR011999
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 23-Nov-21
PLACE OF ACCIDENT : 41 CHAI CHEE STREET CAR PARK



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG /

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMR 2559 T

MSIG Insurance (Singapore) Pte Ltd No. 4 Sheng Jiah Way

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
-----	----------------	-------------------	----------------------------

- | | | | |
|---|---|---------------|------|
| 1 | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. | S/N \$ 360.00 | X |
| 2 | TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE. | S/N \$ 350.00 | 250 |
| 3 | TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED | \$ 2,100.00 | 500 |
| 4 | TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER. | \$ 2,000.00 | 1100 |
| 5 | TO CARRY OUT DIAGNOSTIC CHECK. | S/N \$ 192.00 | ✓ |

TOTAL LABOUR CHARGES : \$ 5,002.00

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 2559 T

ESTIMATED LABOUR CHARGES FOR AC

PARTS & PRICES

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>Regis</i>	1	\$ 1,634.00	+
2	FRONT BUMPER FIXING PARTS <i>new</i>	1	\$ 137.00	+
3	FRONT SPOILER - LH <i>new</i>	1	\$ 100.00	+
4	FRONT BUMPER AIR GUIDE GRILLE - LH <i>lit</i>	1	\$ 211.00	+
5	FRONT BUMPER GRILLE - CENTER <i>new</i>	1	\$ 196.00	+
6	FRONT BUMPER CLOSING ELEMENT <i>new</i>	1	\$ 167.00	+
7	RADIATOR GRILLE	1	\$ 926.00	+
8	RADIATOR CLOSING ELEMENT	1	\$ 161.00	+
9	FRONT BUMPER FOAM FILLER PIECE	1	\$ 118.00	+
10	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 723.00	+
11	FRONT BUMPER GUIDE PROFILE - LH	1	\$ 36.00	+
12	FRONT BUMPER GUIDE SECTION - LH	1	\$ 107.00	+
13	FRONT BUMPER TOP COVER	1	\$ 123.00	+
14	CAUTION STICKER	1	\$ 14.00	+
15	AIRCON STICKER	1	\$ 19.00	+
16	FRONT FENDER - LH <i>Regis</i>	1	\$ 978.00	+
17	FRONT FENDER BRACE - LH	1	\$ 54.00	+
18	FRONT FENDER BRACKET - LH	1	\$ 37.00	+
19	FRONT FENDER BRACKET - LH CENTER <i>new</i>	1	\$ 14.00	+
20	FRONT FENDER BRACKET - LH END <i>new</i>	1	\$ 58.00	+
SUB TOTAL SPARE PARTS		:	\$ 5,813.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMR 2559 T

DAMAGED PARTS & PRICES

S/N PARTS DESCRIPTION QTY S/NETT REMARKS

21	FRONT WHEEL HOUSING LINER	1	TBC	X
22	HEADLIGHT - LH	1	\$ 4,288.00	✓
23	LIFT CYLINDER - LH	1	\$ 142.00	X
24	LIFT CYLINDER HOSE	1	\$ 59.00	X
25	RADIATOR AIR GUIDE - LH	1	\$ 38.00	X
26	FRONT NO PLATE	S/N	\$ 60.00	X
27	SUNDRIES		\$ 300.00	?

TOTAL SPARE PARTS : \$ 10,700.00

TOTAL LABOUR CHARGES : \$ 5,002.00

GRAND TOTAL : \$ 15,702.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : *Adrian Ling*
 SURVEYED DATE : *18/01/22*
 AUTHORISED DATE :
 EXCESS COST :
 LIABILITY :
 REMARKS : *Not Authorised, 04 Days*

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORA KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
 PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

JOHNNY BOO
 BODY REPAIR MANAGER

ALLAN WU
 CLAIMS CONSULTANT