

SembWaste Pte Ltd CO REGN NO 199507280G 30 Hill Street #05-04 Singapore 179360 Tel (65) 6723 3113 Fax (65) 6822 3254 www.sembcorp.com

Our Ref. JC/SW ACC/223/22

18 January 2022

AXA Insurance Singapore Pte Ltd 8 Shenton Way #24-01 AXA Tower Singapore 068811 By Email motor.survey@axa.com.sg

Attention: Claims Department

**Dear Sirs** 

## ACCIDENT INVOLVING XE5992T AND XD2743X ALONG TUAS SOUTH AVE 3 AND TUAS SOUTH AVE 6 JUNCTION ON 13.01.22

We refer to the above subject.

We are the owner of the vehicle number XE5992T which was involved in an accident with the vehicle number XD2743X. We understand that you are the insurer of vehicle number XD2743X at the material time of accident.

We are in view that the accident was caused by the negligence of the driver of vehicle number XD2743X.

We enclose copies of the following documents for your attention:

- Zenith Engineering Pte Ltd Quotation No. QU22-L0054-R01 dated 14.1.22 for the repair of our vehicle XE5992T at S\$14,980.00 inclusive of GST;
- Singapore Accident Statement of our vehicle XE5992T;
- Vehicle Registration Details of our vehicle XE5992T;
- Photos of damages assessment of our vehicle XE5992T by Zenith Engineering Pte Ltd; and
- LTA search of your insured vehicle no. XD2743X.

Please contact our fleet management, Mr Azman at 9186-4590 to make the necessary arrangement to conduct a survey of our damaged vehicle which is located at Zenith Engineering Pte Ltd, 34 Joo Koon Circle, Singapore 629060 within three (3) days from the date of this letter, failing which we shall proceed with the repairs and all cost of repairs shall be borne by you, being the insurer of vehicle no. XD2743X.

Yours faithfully

Joanne Chew Senior Executive Legal & Compliance

Encls.