

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Fievel Foo Wen Yao

Date: 04 Feb 2022

Preliminary Advice

Insured Vehicle No : YL7196M
TP Vehicle No : GBF7469E
Make : MITSUBISHI CANTER
Date of Inspection : 20/01/2022
Inspection At : FASTECH AUTO PTE LTD (HQ)
1 KAKI BUKIT AVE 6, #01-46/48/50 AUTOBAY
SINGAPORE 417883

Accident Date : 18/01/2022
Assignment Date : 21/01/2022
Est. Duration of Repair : 4

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	10,630.00
Revised Amount	:S\$	3,780.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	3,780.00
Lump Sum Repair	:S\$	3,000.00

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	45,000.00
COE / PARF Rebate	:S\$	23,488.00
Salvage Value	:S\$	
Margin for Repair	:S\$	21,512.00

Remarks

- () The vehicle is economical for repair
 - () The vehicle is not economical for repair
 - () Part-by-Part repair
 - (x) Lump Sum repair
- (x) The above survey was conducted on a 'without prejudice' basis.