

RE: SMP8584R DOA 09.01.22

Denise Tay (LKKAUTO) <denisetay@lkkauto.com>

Fri 21/1/2022 10:43 AM

To: claims@mycarworkshop.com.sg <claims@mycarworkshop.com.sg>

Cc: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>; SUR <sur@lkkauto.com>

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle : **SMP8584R (Excess \$3500/-). Lump sum repair**

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

*Our client reserve their rights **not to pay** if there is no valid approval obtained before repair.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>**Sent:** Thursday, 20 January 2022 4:34 PM**To:** Denise Tay (LKKAUTO) <denisetay@lkkauto.com>**Subject:** FW: SMP8584R DOA 09.01.22

From: Accord Auto(Claims) <claims@mycarworkshop.com.sg>**Sent:** Thursday, 20 January 2022 3:44 pm**To:** Kenneth Kong (LKKAUTO) <KennethKong@lkkauto.com>**Subject:** SMP8584R DOA 09.01.22

Dear Kenneth,

Kindly see file attached for the actual estimate.
Pls revise this estimate

Thank you.

Kind regards,

Jacqueline

Accord Auto Services Pte Ltd

10 Ang Mo Kio Ind Park 2A

#03-11 Ang Mo Kio Auto Point
Singapore 568047

Mobile : (65) 9740 0999

Tel : (65) 6481 9517

Fax : (65) 6481 9516

This email is confidential and privileged. If you are not the intended recipient, you must not view, disseminate, use or copy this email. Kindly notify the sender immediately, and delete this email from your system. Thank you.