

6507 3582



XIN YUN AUTO PTE LTD

BLK8 #05-23 Premier, Kaki Bukit Ave4 (415875)

Vehicle No.: XD4937R

RECOMMENDED PARTS

No.	Qty	Part No.	Descriptions	Condition	Repairer	Adjusted
1	1		Safe stop TMA Truck Mounted Attenuators	buc	70,000.00	
						11W \$24K x 50% as FCI method 17000 48,000 50,000 60,000
Sub Total (\$\$):					70,000.00	-
Total Parts (\$\$):					70,000.00	-

RECOMMENDED SPECIAL NETT ITEMS

No.	Qty	Part No.	Descriptions	Condition	Repairer	Adjusted
1	1		Supply of metal bracket for the TMA installation		1,500.00	X
2	2		Flashing arrow led light board for both side		1,200.00	X
3	1		Xenon strobe light on top		600.00	X
4	1		Danger keep clear -yellow green type with sign panel		800.00	200
5	1		Yellow green type wide angel prismatic sticker "Split Chevron"		900.00	300
6	1		Yellow green type wide angle prismatic sticker with truck number		600.00	X
7	1		Customized TMA ID plate		400.00	X
Sub Total (\$\$):					6,000.00	-

RECOMMENDED LABOUR

No.	Descriptions	Repairer	Adjusted
LABOUR ITEMS			
1	TO dismantle and install new TMA, focus on damaged portin, panel beating and reshapar, straighten, orientate and align the whole repair	5,000.00	1200
2	To do the alignment, after the TMA installation	300.00	X
3	To do all the led woring light setting up work and check wiring	1,000.00	60
4	To installl the yellow green type sign panel	500.00	X
5	Remove exiting TMA, remove the old type of frame and old type TMA support	2,000.00	X
6	Remove and install all new set of sticker	800.00	400
7	Install TMA ID Plate	300.00	X
PAINTWORK LABOUR			
7	Supply spray material to TMA and rear damaged portion	3,000.00	X
Total Labour (\$\$):		12,900.00	-

COST OF CLAIMS

		Repairer	Adjusted
1	PARTS	70,000.00	-
2	SPECIAL NETT ITEMS	6,000.00	-
3	LABOUR	9,900.00	-
4	PAINTWORK LABOUR	3,000.00	-

Gross Total (\$\$): 88,900.00

GST 7.00% (\$\$): -

Total Amount (\$\$): 88,900.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

(Confidential and privileged for use by insurers and their legal advisers)

Acknowledged by Repairer

Signature:

Date:

Rasul
 Hp 90010068
 5 days
 P/P
 27/01/22 @ 1010
 EXCESS: TBA
 Repairer
 Resy after repair