

SM AUTOMOTIVE

Block C, 1 Kaki Bukit Avenue 6 #01-43 Singapore 417883

Email: SM_AUTOMOTIVE@HOTMAIL.COM

Tel: (65) 6747 9241 Fax: (65) 6741 7276

RCB No.: 53231488C

19/01/2021

Blk 1 Kaki Bukit Ave 6

01-43

Singapore 417883

Accident date: 19/01/2021

Estimated repair cost for vehicle no: SLS4475U KIA FORTE K3 1.6A

TPAXA

Xiao Tony

CHASSIS: KNAFJ411MJ5743852 (2017)

S/n	Qty	Items	U/price	Amount
1	1	FRONT BUMPER <i>Dented</i>	\$953.40	<u>\$953.40</u> 631
2	1	FRONT BUMPER REINFORCEMENT <i>Dented</i>	\$485.60	\$485.60 ✓
3	1	FRONT BUMPER SPONGE <i>Cushed</i>	\$240.70	<u>\$240.70</u> 85
4	1	FRONT BUMPER LOWER BEAM <i>New</i>	\$258.60	\$258.60 ✓
5	1	FRONT BUMPER SIDE RETAINER LH <i>Dented</i>	\$58.70	\$58.70 ✓
6	1	FRONT BUMPER SIDE GARNISH LH <i>New</i>	\$145.60	\$145.60 ✓
7	1	FRONT BUMPER FOG LAMP COVER LH <i>New</i>	\$190.70	\$190.70 ✓
8	1	FRONT HEADLAMP LH <i>Cushed</i>	\$1,894.60	<u>\$1,894.60</u> 1350
9	1	FRONT HEADLAMP LOWER BRACKET LH <i>New</i>	\$78.90	\$78.90 +
10	1	FRONT FENDER LH <i>Dented</i>	\$525.60	\$525.60 ✓
11	1	FRONT FENDER INNER COWLING LH <i>New</i>	\$180.50	\$180.50 +
12	1	FRONT SUPPORT PANEL <i>Cushed</i>	\$845.70	<u>\$845.70</u> 652
13	1	FRONT SHOCK ABSORBER LH <i>Best</i>	\$596.30	\$596.30 ✓ 336
14	1	FRONT LOWER ARM LH <i>Best</i>	\$485.30	\$485.30 ✓ 398
15	1	FRONT KNUCKLER ARM LH <i>Damaged</i>	\$656.40	<u>\$656.40</u> 392
16	1	FRONT KNUCKLER ARM BEARING LH <i>Dented</i>	\$233.50	\$233.50 ✓
17	1	STEERING RACK & PINION <i>3 NP</i>	\$2,504.60	\$2,504.60 +
18	1	FRONT STABILIZER LINK LH <i>3 m</i>	\$177.40	\$177.40 +

TOTAL : \$10,512.10

LESS 10 % \$1,051.21

SUB-TOTAL : \$9,460.89

\$147.40

4632.66

S/N	Qty	ITEMS / SPECIAL NETT	U/price	Amount
1	1	FRONT BUMPER CLIPS <i>new</i>	\$80.00	\$80.00 30
2	1	FRONT FENDER INNER COWLING CLIPS LH <i>new</i>	\$60.00	\$60.00 4
3	1	LH FRONT SPORT RIM <i>lt</i>	\$650.00	\$650.00 400
4	1	LH FRONT TYRE <i>lt new</i>	\$195.00	\$195.00 4

430

TOTAL: \$985.00

TOTAL PARTS : \$10,445.89

Labour charges

- 1 LABOUR FOR PANEL BEATING
- 2 LABOUR FOR SPRAYPAINTING
- 3 WIRING CHECK
- 4 TO APPLY TUFF COATING/RUST PROOF ACCIDENT AREAS
- 5 LABOUR FOR REMOVE & RENEW LH FRONT UNDER CARRIAGE
- 6 TO CONDUCT WHEEL ALIGNMENT

~~\$1,400.00~~ 700
~~\$1,000.00~~ 400
~~\$80.00~~ 30
~~\$300.00~~ 40
~~\$400.00~~ 220
~~\$180.00~~ 80

1470

Subtotal :- \$2,780.00

Total:- \$13,225.89

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Adrian L

l/s 20/01/22

OS Pays

total: 6532.66

l/s: 52K

52K

