

Claim	S1M03H4N
Reference	CS3/ASM21009735/Bqy3e2-1 
Loss Date	1 September 2021
Vendor Name	LKK AUTO CONSULTANTS PTE LTD (TP)
Type of Loss	Third Party Vehicle Damage
Report Date	2 Sep 2021 5:55:22 PM
Request Date	17 September 2021
Due Date	
Services	Pre-Repair Survey

Actions

Next Step

Wait for: Approve invoice

Add Invoice

Vehicle Information

Incident

SDV4007S

Vehicle

Registration #

Make

TPVD Volvo

Model

Xc60

Service Address

, , ,

Primary Contact/Insured

COMFORT TRANSPORTATION PTE LTD

383 SIN MING DRIVE, 575717, Singapore

65551188

Additional Instructions

- Messages5
- Invoices
- History
- Documents
- Assessment
- Metrics
- Notes

Document Type

Document SubType

+ Upload Documents

Already Attached

NAME		DATE UPLOADED			
NAME		TYPE	SUBTYPE	AUTHOR	DATE UPLOADED
 S1M03H4N_[CTPL-Reported - TPPD] _Accident Involving SHA7895M & SDV4007S_along_CROSS JUNCTION OF BRAS BASAH RD AND NTH BRIDGE RD on 01/09/2021 21:30_PersonalAutoLine.eml		Other	Other	do not reply	

[FAQ](#)[English \(SG\) ▼](#)[Elaine Kuan ▼](#)

TYPE

SUBTYPE

AUTHOR

DATE
UPLOADED[Service Requests](#)[t Involving](#)

[SMITHSON ROAD AND NTH BRIDGE RD on 01/09/2021](#)
[21:30_PersonalAutoLine.eml](#)

Other

Other

do not reply

[ASM-LKKInvoice-AC2200585.pdf.pdf](#)

Email Sent

Surveyor/
Assessor
expenseLKK AUTO
CONSULTANTS
PTE LTD (TP)28 January
2022 [LKKLetter-SDV 4007S.pdf.pdf](#)Reports &
StatementSurvey
ReportLKK AUTO
CONSULTANTS
PTE LTD (TP)28 January
2022 [LKKAdjustment.pdf.pdf](#)Reports &
StatementSurvey
ReportLKK AUTO
CONSULTANTS
PTE LTD (TP)28 January
2022 [Survey report.pdf.pdf](#)Reports &
StatementSurvey
Report

TEO Kitty

20 January
2022 [ASM-LKKInvoice-AC2106939.pdf.pdf](#)

Email Sent

Surveyor/
Assessor
expenseLKK AUTO
CONSULTANTS
PTE LTD (TP)7 October
2021

[FAQ](#)[English \(SG\) ▼](#)[Elaine Kuan ▼](#)[Service Requests](#)

TYPE

SUBTYPE

AUTHOR

DATE
UPLOADEDReports &
StatementSurvey
ReportLKK AUTO
CONSULTANTS
PTE LTD (TP)7 October
2021 [LKKPhoto.pdf.pdf](#)

Evidence

Photos

LKK AUTO
CONSULTANTS
PTE LTD (TP)7 October
2021 [Resurvey Photo-1.pdf.pdf](#)

Evidence

Photos

LKK AUTO
CONSULTANTS
PTE LTD (TP)7 October
2021 [Resurvey Photo-2.pdf.pdf](#)

Evidence

Photos

LKK AUTO
CONSULTANTS
PTE LTD (TP)7 October
2021 [AXA Immediate Advice - SDV4007S \(PRS\).pdf.pdf](#)Reports &
Statement

Others

LKK AUTO
CONSULTANTS
PTE LTD (TP)4 October
2021 [SURVEYOR APPOINTED.msg.msg](#)Letters and
CorrespondenceSolicitor /
AdvocateVISHNU
BATHAM
Shekhar17
September
2021

[FAQ](#)[English \(SG\) ▼](#)[Elaine Kuan ▼](#)[Service Requests](#)[1M03H4N for](#)[vehicle SDV4007S.html.html](#)

TYPE

SUBTYPE

AUTHOR

DATE
UPLOADED

Email Sent

VISHNU
BATHAM
Shekhar17
September
2021 [LIST OF SURVEYOR SENT.msg.msg](#)Letters and
CorrespondenceSolicitor /
AdvocateVISHNU
BATHAM
Shekhar17
September
2021 [CTPL-REPORTED-TPPD.msg.msg](#)Letters and
CorrespondencePolicy
Holders /
InsuredVISHNU
BATHAM
Shekhar17
September
2021 [EMAIL TP REG.pdf.pdf](#)Letters and
CorrespondenceSolicitor /
AdvocateVISHNU
BATHAM
Shekhar17
September
2021 [EMAIL TP REG.msg.msg](#)Letters and
CorrespondenceSolicitor /
AdvocateVISHNU
BATHAM
Shekhar17
September
2021 [GIA SDV4007S TP.pdf.pdf](#)Reports &
StatementGIA
ReportVISHNU
BATHAM
Shekhar17
September
2021

[FAQ](#)[English \(SG\) ▼](#)[Elaine Kuan ▼](#)[Service Requests](#)

TYPE

SUBTYPE

AUTHOR

DATE
UPLOADED

Evidence

Videos

TEO Kitty

17
September
2021[SHA7895M INSD GIA.pdf.pdf](#)Reports &
StatementAccident
statementSTACEY Ng Pei
Sze 22
September
2021