



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 20/01/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZVW50R	AHXEBW Q2	13/01/2017	SLK3541K	0	12900	75/DS/SLK3541K
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU603543723		2ZRR990124	60	Ng Mei Yen	--/--/----		0.00 --/--/---- 0.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:GBL524T ACC DATE:18/01/22 TOW IN:18/01/22 EXCESS: DATE-IN: DATE SURVEY: NO OF REPAIR DAYS: BY: AUTHORISED ON:				100.00	
2	Z	BP-SLANT SUPPLY SEALANT (NETT) FOR REAR RH DOOR				60.00	
3	S	BP-SUBLET TO REPLACE REAR RH TYRE AND SPORT-RIM TO BALANCE.				180.00	
4	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00	
5	B	BP-MECH2 TO CONDUCT WHEEL ALIGNMENT CHECK.				180.00	
6	B	BP-MECH2 R/I REAR SUSPENSION TO CHECK AND REPLACE NECESSARY PARTS.				1440.00	
7	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK.				122.40	
8	B	BP-LAB2 R/I REAR CARPET,TRIMMINH,REAR SEATS AND ALL OTHER ATTACHMENT TO FACILIATE REPAIRS.				720.00	
9	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.				7200.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts Labour Sublet Lubrication/Fluid Others		Less
							Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No.				
			0				
			Document Date				
			20/01/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZVW50R	AHXEBW Q2	13/01/2017	SLK3541K	0	12900	75/DS/SLK3541K

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU603543723	2ZRR990124	60	Ng Mei Yen	--/--/----	0.00 --/--/----

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
10	B	BP-RES2 TO SPRAY PAINT OH REAR ACCIDENT AFFECTED AREAS.				5900.00
11	1	U52159-47913 COVER, RR BUMPER	1.00	469.50		469.50
12	2	U52575-47040 RETAINER, RR BUMPER	1.00	124.90		124.90
13	3	U52576-47040 RETAINER, RR BUMPER	1.00	123.60		123.60
14	4	U52591-47050 SEAL, RR BUMPER	1.00	93.50		93.50
15	5	U52592-47040 SEAL, RR BUMPER	1.00	93.50		93.50
16	6	U52023-47030 REINFORCEMENT	1.00	353.10		353.10
17	7	U52453-47010 GUARD, RR BUMPER,	1.00	611.30		611.30
18	8	U52565-47900 FILLER, RR BUMPER	1.00	131.10		131.10
19	9	U52566-47900 FILLER, RR BUMPER	1.00	131.10		131.10
20	0	U58307-47090 PANEL SUB-ASSY, BODY	1.00	689.70		689.70
21	1	U58311-47130 PAN, RR FLOOR	1.00	618.90		618.90
22	2	U58398-47050 COVER, FLOOR UNDER,	1.00	185.60		185.60
23	3	U90467-17026 A0 CLIP	1.00	3.50		3.50
24	4	U58399-47030 COVER, FLOOR UNDER,	1.00	256.50		256.50
25	5	U61601-47150 PANEL SUB-ASSY,	1.00	925.90		925.90
26	6	U61607-47902 PANEL S/A, QTR W/H,	1.00	576.20		576.20
27	7	U65637-47060 LINER, RR WHEEL	1.00	148.00		148.00
28	8	U61631-47070 PANEL, QUARTER WHEEL	1.00	314.20		314.20

For & on behalf of	Customer's Signature	Charge Summary	Total
Borneo Motors (Singapore) Pte Ltd			
	Please acknowledge receipt of vehicle	Parts	
		Labour	
		Sublet	
		Lubrication/Fluid	
		Others	
			Less
			Amount Due

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
THIRD PARTY CLAIM			S1000020 / TPCLAIM		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No.				
			0				
			Document Date				
			20/01/2022				

Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2016	ZVW50R	AHXEBW Q2	13/01/2017	SLK3541K	0	12900	75/DS/SLK3541K

Chassis No.	Engine No.	Terms	SA / Counter	Vehicle In	Collected On
JTDKB3FU603543723	2ZRR990124	60	Ng Mei Yen	--/--/----	0.00

L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount
29	9	U61601-47150 PANEL SUB-ASSY,	1.00	925.90		925.90
30	0	T08826-08115 PANEL BONDING AD	1.00	267.20		267.20
31	1	U62940-47010 DUCT ASSY, QUARTER	1.00	70.90		70.90
32	2	U58745-47030 PROTECTOR, QUARTER	1.00	24.40		24.40
33	3	U62505-47011 COVER SUB-ASSY,	1.00	219.50		219.50
34	4	U81551-47283 LENS & BODY, RR	1.00	479.30		479.30
35	5	U81497-47020 COVER, RR	1.00	68.50		68.50
36	6	U81581-47011 LENS & BODY, RR	1.00	532.00		532.00
37	7	U67003-47211 PANEL SUB-ASSY, RR	1.00	1371.80		1371.80
38	8	U75763-47010 MOULDING, RR DOOR	1.00	97.90		97.90
39	9	U75765-47010 MOULDING, RR DOOR	1.00	41.00		41.00
40	0	U75403-48010 EMBLEM SUB-ASSY,	1.00	76.00		76.00
41	1	U75441-47130 PLATE, LUGGAGE COMPT	1.00	58.00		58.00
42	2	U75442-47130 PLATE, LUGGAGE COMPT	1.00	58.00		58.00
43	3	U42611-47450 WHEEL, DISC	1.00	1995.20		1995.20
44	4	YTDG19-565R1 5 GRAB DUNLOP 195-65R15	1.00	88.00		88.00
45	5	U75977-47080 STRIPE, RR DOOR,	1.00	23.20		23.20
46	6	U75987-47060 STRIPE, RR DOOR,	1.00	37.00		37.00
47	7	U75979-47070 STRIPE, RR DOOR,	1.00	16.30		16.30

For & on behalf of	Customer's Signature	Charge Summary	Total	28,382.60
Borneo Motors (Singapore) Pte Ltd				
	Please acknowledge receipt of vehicle	Parts 12,300.20	GST 7.00%	1,986.78
		Labour 15,902.40	Less	0.00
		Sublet 180.00		
		Lubrication/Fluid 0.00		
		Others 0.00	Amount Due	30,369.38

Customer Copy