

OPTIMA WERKZ™**SINGAPORE****OPTIMA WERKZ PTE LTD**

Co. Reg. No. 201212455W

www.ow.sg

/OptimaWerkz

/OptimaWerkz

Date: 20.01.2022

Vehicle No: SGD4466J

Model: TESLA MODEL 3 STANDARD RANGE

Chassis: LRW3F7FA1MC385378

Reg.Year: 2021

Third Party Insurer: AIG

Third Party Veh No: SBV2121G

Date of Accident: 19.01.2022

Estimator: Victor

Surveyor:

ESTIMATE

NO.	DESCRIPTION	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER	1		<i>Bu / Re</i> \$763.55 ✓
2	FRONT BUMPER SIDE BRACKET RH	1		\$29.33 ✓
3	FRONT FENDER BRACKET RH	1		\$21.83 ✓
4	FRONT BUMPER UNDERCOVER	1		<i>Re</i> \$216.92 X
5	HEADLAMP RH	1		\$1,308.41 ✓
6	HEADLAMP BRACKET RH	1		<i>Re</i> \$65.93 X
7	FOG LAMP ASSY RH	1		<i>Re</i> \$291.03 X
8	FRONT FENDER RH	1		<i>Bu</i> \$548.60 ✓
9	FRONT SENSORS	2	\$198.88	\$397.76 ✓
10	FRONT SENSORS HOLDER	2	\$20.67	\$41.34 ✓
11	FRONT RIM 19 INCH	1		<i>Re</i> \$978.50 ✓
12	FRONT FENDER SHIELD RH	1		<i>cm</i> \$176.82 ✓
13	FRONT KNUCKLE ARM RH	1		\$520.56 ✓
14	FRONT BEARING HUB RH	1		\$189.53 ✓
15	FRONT UPPER CONTROL ARM RH	1		\$156.82 ✓
16	FRONT LOWER ARM RH	1		\$264.30 ✓
17	FRONT LOWER LATERAL LINK RH	1		\$283.64 ✓
18	FRONT SWAYBAR LINKAGE RH	1		<i>Re</i> \$18.13 X
19	STEERING GEAR TIE ROD RH	1		<i>Re</i> \$171.50 X
20	FRONT DAMPER RH	1		<i>Re</i> \$277.57 X
SUB TOTAL				\$6,722.07
LESS 10%				-\$672.21
PARTS TOTAL				\$6,049.86

NO.	SPECIAL NETT	QTY	UNIT S\$	AMOUNT S\$
1	FRONT BUMPER CLIPS	1		<i>Re</i> \$100.00 ✓
2	FRONT UNDER COVER CLIPS	1		<i>Re</i> \$120.00 X
3	FRONT INNER SHIELD CLIPS	1		<i>Re</i> \$50.00 ✓
S/N TOTAL				\$270.00

LABOUR CHARGES:

LABOUR CHARGES TO REMOVE, REPLACE, REFIX, REPAIR FRONT ACCIDENT AREA.

\$1,000.00

4801

Head office

6 Kung Chong Road Singapore 159143

Branch

9A Serangoon North Ave 5 Singapore 554600

Branch (Motor Insurance Claims)

Blk 10 Ang Mo Kio Ind. Park 2A #01-05 Singapore 568047
Tel: (+65) 6481 1522 | Fax: (+65) 6481 1011

Date: 20.01.2022
Vehicle No: SGD4466J
Model: TESLA MODEL 3 STANDARD RANGE
Chassis: LRW3F7FA1MC385378
Reg.Year: 2021

Third Party Insurer: DIRECT ASIA
Third Party Veh No: SBV2121G
Date of Accident: 19.01.2022
Estimator: Victor
Surveyor:

LABOUR CHARGES TO SUPPLY PAINT & FURNISHING MATERIALS AT FRONT ACCIDENT ARI	\$1,000.00	4801
TO REMOVE AND INSTALL FRONT UNDERCARRIAGE.	\$250.00	7
TO CONDUCT WHEEL ALIGNMENT AND BALANCING.	\$150.00	601
TO CHECK WIRING & ELECTRICAL SYSTEM & ETC.	\$200.00	201
TO DIAGNOSIS FAULT CODE & RESET MEMORY.	\$350.00	?
LABOUR TOTAL	\$2,950.00	

TOTAL \$9,269.86

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: