**FASTECH AUTO PTE LTD** 

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No: 200006262D

LKK Auto Consultants hence notify the Repairer of the following: To resurvey before/after spray painting

To display damaged part(s) during resurvey

Parts prices are subject to confirmation

Third party survey is on a "Without Prejudice" basis

No illegal modification(s) is allowed

Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## **VEHICLE No:SMR 7846G**

1PC	FRONT BUMPER 70/De	1615.00	\$2,480.00
2PCS	FRONT BUMPER PDC SENSORS @\$285.00 Suc		\$570.00 ×
1PC	FRONT BUMPER BEAM		\$685.00 >
1PC	FRONT BUMPER CHROME MOULDING	650.00	\$1,021.00
1PC	FRONT BUMPER SPONGE	108.50	_\$288.00
1PC	FRONT BUMPER CENTRE GRILLE	, - 4 - 5	\$254.00 🗶
1PC	FRONT BUMPER SIDE CHROME		\$688.10 ×
2PCS	FRONT BUMPER SIDE RETAINERS @\$105.00	1	\$210.00 ×
1PC	FRONT GRILLE ASSY	00.0221	\$1,645.10
1PC	FRONT GRILLE LOGO SCA	1330.00	\$250.00 /
1PC	FRONT GRILLE RADAR SENSOR SVC		\$1,200.00 ×
2PCS	HEADLAMP ASSYS @\$4900.00	4027.3042-808460	
1PC	FRONT SUPPORT PANEL	3-4,00	\$1,021.00 🗙
1PC	FRONT SUPPORT PANEL TOP GARNISH		\$388.90
1PC	1/20	Pen-1	\$1,845.25
1PC		F55-60 F65-20	\$645.25
1PC	CONDENCED	202-20	\$1,450.00 ×
1PC	RADIATOR 11	6	\$2,180.00 >
1PC	HYBRID RADIATOR A	252	\$1,605.00 >
110	THE REPORT OF THE PARTY OF THE		\$28,226.60
	S.NETT		,
	1 TT		
1SET	FRONT BUMPER CLIPS		\$50.00
1PC	FRONT LICENCE PLATE 3uf		\$50.00 40
1SET	FRONT GRILLE CLIPS ALL		\$50.00
1BOL	RADIATOR COOLANT		\$50.00 X
1BOL	AIR CON OIL		\$50.00
			2.0
	TO CHECK WIRING		\$50.00 20
	TO RESET & REPROGRAMME SYSTEM		\$180.00
	TO DISMANTLE & REFIX FRONT PDC SENSOR		\$100.00
	TO SPARY RUST PROOFING		\$100.00 3
	TO REFILL AIR CON GAS		\$120.00×
	LABOUR FOR PANEL BEATING & REPLACED PARTS	S	\$1,080.00 500
	TO PUTTY & SPRAY PAINTING		\$1,500.00 600
		TOTAL	\$31,606.60