

⏪	<	1 of 2 ?	>	⏩	↺	↻	100% ▼	🖨	📄	Find Next
---	---	----------	---	---	---	---	--------	---	---	-------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
GREAT AMERICAN INSURANCE COMPANY			Ref:	CS3/GAI22000779/Vvf3
3 TEMASEK AVENUE			Date:	21/01/2022
#16-01 CENTENNIAL TOWER				
SINGAPORE 039190			Code:	GAI
1. Policy Particulars :- (THIRD PARTY CLAIM)				
Insured Veh.	PA 6585U	Veh. Inspected	FBN 7600A	
Policy No.		Coverage (\$)	0.00	
Claim No.	CLMOMVC000004108,	Excess (\$)	0.00	
Assign From	JANELLE TAN	Assign Date	21/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	c.c		0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/01/2022	Inspection Date	21/01/2022	
Survey held at	CANDYMOTOR WORKSHOP PTE LTD 25 KAKI BUKIT ROAD 4 #01-83 SYNERGY @ KB SINGAPORE 417800			
5a. Remarks				
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.				