



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22000787/Eqf3n2	
			Date: 31/03/2022	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHB 1038E	Veh. Inspected	SKQ 586G	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/01/22/2018	Excess (\$)	0.00	
Assign From	HUA YEN	Assign Date	24/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	BMW 216I	c.c	1499	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	WBA6V12090ED05675	Colour	WHITE	
Odometer	80871 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	205/55 R17	MICHELIN	5 mm	
L/H Front Tyre	205/55 R17	MICHELIN	5 mm	
R/H Rear Tyre	205/55 R17	MICHELIN	5 mm	
L/H Rear Tyre	205/55 R17	MICHELIN	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/01/2022	Inspection Date	04/02/2022	
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	