

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



Vehicle No : SMU 3327 D

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0053/2022/JT
DATE : 21-Jan-22
WIP : 64409

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MS SAMANTHA LAW SIEW YEN
ADDRESS : 5 FORTH STREET
SINGAPORE 458259
TELEPHONE : HP +65 97546269
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210111716
VEHICLE NO : SCY 1092 K
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 17/9/2021
ENGINE NO : DKY 015840
CHASSIS NO : WAUZZZF27MN094832
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Jan-22
PLACE OF ACCIDENT : PIE/ JURONG WEST AVE 2/ CORPORATION ROAD

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCY 1092 K

SURVEYOR'S	S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S	RECOMMENDATIONS
	1	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY.	S/N \$ 280.00 ✓		
	2	TO RESPRAY LHS WING MIRROR COVER.	\$ 500.00 180		
	3	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓		
		TOTAL LABOUR CHARGES	: \$ 972.00		

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

55 UBI ROAD 1, SINGAPORE 408699
TEL: 6366 2323 FAX: 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ATED LABOUR

MATERIAL LIST FOR ACCIDENT VEHICLE REGN/NO. SCY 1092 K

ESTIMATED LABOUR CHARGES FOR

TS & PRICES

ESTIMATED

DAMAGED PARTS & PRICES

	S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21		WING MIRROR MOUNTING - LH <i>Distorted</i>	1	\$ 3,069.00	✓ 2455.20
22		WING MIRROR CAP - LH <i>Missing</i>	1	\$ 348.00	✓ 278
23		WING MIRROR GLASS - LH <i>Missing</i>	1	\$ 1,298.00	✓ 108.4
24		SUNDRIES <i>?</i>		\$ nn 50.00	? X
TOTAL SPARE PARTS			:	\$ 4,765.00	
TOTAL LABOUR CHARGES			:	\$ 972.00	
GRAND TOTAL			:	\$ 5,737.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

VEHICLE LIST FOR ACCIDENT VEHICLE SERVICED NO. SCY 1092 K

ESTIMATED LABOUR MATERIAL LIST FOR ACCIDENT VEHICLE

NAME

SURVEYED DATE

AUTHORISED DATE

EXCESS COST

LIABILITY

REMARKS

Adnan
21/09/22
Not Authorised, 02 Days

PLEASE NOTE

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: