

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0053/2022/JT
DATE : 21-Jan-22
WIP : 64409

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/1/22

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Adrian,

2 days - ok - Jy - 13 Apr 22

OWNER'S NAME : MS SAMANTHA LAW SIEW YEN
ADDRESS : 5 FORTH STREET
SINGAPORE 458259
TELEPHONE : HP +65 97546269
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 7210111716
VEHICLE NO : **SCY 1092 K**
MODEL CODE : AUDI A6 DESIGN 2.0 TFSI S
MODEL YEAR : 17/09/2021
ENGINE NO : DKY 015840
CHASSIS NO : WAUZZZF27MN094832
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 20-Jan-22
PLACE OF ACCIDENT : PIE/ JURONG WEST AVE 2/ CORPORATION ROAD

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SCY 1092 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND RENEW LHS WING MIRROR ASSY.	S/N \$	280.00	\$	280.00
2	TO RESPRAY LHS WING MIRROR COVER.	\$	500.00	\$	180.00
3	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 972.00	\$	652.00

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SCY 1092 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	WING MIRROR MOUNTING - LH	1	\$ 3,069.00	\$ 2,455.20
22	WING MIRROR CAP - LH	1	\$ 348.00	\$ 278.00
23	WING MIRROR GLASS - LH	1	\$ 1,298.00	\$ 1,038.40
	SUPP - see attachment			\$ 101.60
24	SUNDRIES		\$ 50.00	
TOTAL SPARE PARTS		:	\$ 4,765.00	\$ 3,873.20
TOTAL LABOUR CHARGES		:	\$ 972.00	\$ 652.00
GRAND TOTAL		:	\$ 5,737.00	\$ 4,525.20

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd 78 Shenton Way #07-16 AIG Building Singapore 079120 Attn: Mr. Adrian Ling - Motor Claims Dept Tel: 6841 0055 / Fax: 6256 4315		Estimate No. Date Service Advisor Pages Regn No Model No	PA/OD/0053/2022/JT 26-Jan-22 CHANG 1 of 1 SCY 1092 K AUDI A6 DESIGN 2.0 TFSI	
Quantity	Description		Unit Price	Amount
<u>Parts</u>				
1	SIDE MIRROR SUNDRY PARTS SET	1	\$ 127.00	\$ 101.60
GRAND TOTAL			\$ 127.00	\$ 101.60

For Premium Automobiles Pte Ltd

Authorized Signature