

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6842 1183

EMAIL : NORA.KHAT@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SFU 5183 R

|                      |                                                         | DAMAGED PARTS & PRICES |              |         |             |
|----------------------|---------------------------------------------------------|------------------------|--------------|---------|-------------|
| S/N                  | PARTS DESCRIPTION                                       | QTY                    | S/NETT       | REMARKS |             |
| 41                   | LIFT CYLINDER HOSE <i>new torn</i>                      | 1                      | \$ 92.00     | ✓       | <i>R.S.</i> |
| 42                   | LOCK CARRIER <i>crushed</i>                             | 1                      | \$ 1,412.00  | ✓       |             |
| 43                   | A/C CONDENSER ?                                         | 1                      | \$ 569.00    | ?       |             |
| 44                   | OUTSIDE TEMPERATURE SENSOR BRACKET ?                    | 1                      | \$ 9.00      | ?       |             |
| 45                   | ADDITIONAL RADIATOR ?                                   | 1                      | \$ 982.00    | ?       |             |
| 46                   | RADIATOR ?                                              | 1                      | \$ 1,090.00  | ?       |             |
| 47                   | RADIATOR RUBBER BUSH - UPPER <i>new</i>                 | 2                      | \$ 90.00     | +       |             |
| 48                   | RADIATOR BUSH - LOWER <i>new</i>                        | 2                      | \$ 22.00     | +       |             |
| 49                   | RADIATOR COOLANT <i>new</i>                             | 6                      | \$ 282.00    | ✓       |             |
| 50                   | RADIATOR AIR GUIDE - LH / RH ?                          | 2                      | \$ 86.00     | ?       |             |
| 51                   | RADIATOR AIR GUIDE - UPPER / LOWER ?                    | 2                      | \$ 96.00     | ?       |             |
| 52                   | FRONT WHEEL HOUSING LINER - LH / RH <i>new</i>          | 2                      | \$ 520.00    | +       |             |
| 53                   | FRONT WHEEL HOUSING LINER - ATTACHMENT PARTS <i>new</i> | 1                      | \$ 105.00    | +       |             |
| 54                   | FRONT WHEEL HOUSING LINER COVER - LH / RH <i>new</i>    | 2                      | \$ 36.00     | +       |             |
| 55                   | FRONT WHEEL ARCH COVER - LH / RH <i>new</i>             | 2                      | \$ 566.00    | ✓       |             |
| 56                   | FRONT NO PLATE <i>dented</i>                            | S/N                    | \$ 60.00     | ✓       |             |
| 57                   | SUNDRIES ?                                              |                        | \$ 350.00    | ?       |             |
| TOTAL SPARE PARTS    |                                                         | :                      | \$ 33,825.00 |         |             |
| TOTAL LABOUR CHARGES |                                                         | :                      | \$ 12,772.00 |         |             |
| GRAND TOTAL          |                                                         | :                      | \$ 46,597.00 |         |             |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
SPARE PARTS ARE SPECIAL NETT.

*Adrian Lim,  
Resurveyed  
R.S.*