(08/11/13) wef REF: CS A IS 22	202799/0.1/2 C
ASS. REC. BY: '(MXV)	
ASSI	GNMENT COEXPIRY: 2025/may AP
From: Date:	Veh Nó: SJW 783(計 Yr Regn: 2010 / 本化
Estimated Cost:	Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
OD TP / WS / TP RES / OD RES / EVA / INV / MV	Truck / Trailer or
To Inspect Vehicle No: 50 7831H	Make: KIN CERATO EX FOR TE 1.6 L A/C.C 1591
at Workshop m/s Auro Nosuce P/L	Colour RUCK A/C: Insured / Std / NI / NA
of 6, MARSILIAN LANG	Sp.Reading 7/Radio: Insured / Std / NI / NA
Insured: AIS	Eng/No:
Policy No.	C/No: KNAFU411MA5200352.
Claims No.	Gen. Cond: Good /Fair / Poor / Burnt
Sum Insured: Excess: This	Steering: Iporder / Jammed / Leaked / Burnt or
(Client's Record)	Brake: (norder / Jammed / Leaked / Burnt or
Make of Veh:	Modi: Nil /S/Rim / STD A/Rim or
	Tyre Size: F: (95/15/15
(Policy Condition)	R:
Remark: The veh had commenced its N/S O/S	BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
repair at the time of inspection.	TOYO/YOKO or FIRE-ZA
Bal. or Market Value:	Front Rear
IDAC Accident Rport: Consistent? : Yes or No	R/Bal. 6 mm
GIA / PR Seen: Consistent? : Yes or No	L/Bal. (mm L/Bal. mm
Est. Repairs: days Res.: Yes or No	D.O.A. 18 01 22 D.O.I. 24 01 22
Lum Sum: % 3 Val.: Yes or No	Survey held at Awo \www.
CA / (REV) / REP. / 24 HRS	Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
Vehicle: IN / OUT Date: Person Contacted:	OS FRET
Date / Time Action / Instruction	The U/C / Chassis frame / Body Structure affected due to collision.
REPAR LIMIT 15K	<u> </u>
	· · · · · · · · · · · · · · · · · · ·
	Days Of Repair:
	Resurvey No. of Trip: Survey Fee:
Date/Time, File Return to?	Transportation:
2) Add Fee	:: Site Insp (\$
	: Interview (\$). Photos
Report Format :	: Tech. Invs (\$) Others
Lump Sum / I.B.I: (\$:Weekend (\$

TOTAL



Auto Insure Pte. Ltd.

6 Marsiling Lane Singapore (739145)

E: claims01@autoinsure.com.sg

W: www.autoinsure.com.sg T: 3157 2626 F: 6368 0081

GST No.: 201437380M

Page No.1

AUTOMOBILE ASSESSMENT REPORT

Our Ref: SJW7831H (SIEW)

BY EMAIL ONLY

(claims01@autoinsure.com.sg)

Our Ref: 33007831H (31EVV

Date:

21-Jan-22

ATTENTION: MOTOR CLAIMS DEPT

Allianz Insurance Singapore Pte. Ltd

79 Robinson Road

#09-01.

Singapore 068897

Assessed Vehicle No

: SJW7831H

Car Make and Model

: KIA CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR

Date of Accident

: 18-Jan-22

Date of Assessment

: 21-Jan-22

We have carried out a physical assessment of SJW7831H at our workshop Auto Insure Pte Ltd sustained damages to the FRONT RH portion of the vehicle.

4. DESCRIPTION OF DAMAGE

At the time of the inspection observed that this vehicle had sustained damages to the FRONT RH portion of the vehicle.

Please see attached schedule for details.

Remarks: NIL

Estimated Amount

P/P

Adjusted Amount

\$ 11,714.68

Est. Repair Days

9

Pursuant to your instruction, we have AUTHORIZED to repair.

The assessment was conducted on a "WITHOUT PREJUDICE" basis.

If we are not notified of anything within 14 Days from the date hereof, this report shall be treated as correct.

Disclaimer

This report is intended for the exclusive use of the adressee solely in relation to the loss of occurrence in which the assessd vehicle is involved.

No liability or responsibilty whatsoever shall be held by

AUTO INSURE PTE. LTD. For any reliance on this report by any third party.

Our Ref: SJW7831H

PARTS REPLACEMENT - LIST ITEMS 1	s/NO	QTY	DESCRIPTIONS	ASSESSED	EST. BY WORKSHOP		
1	3/110		DESCRIPTIONS	CONDITION	EST. BY WURKSHUP		
S			PARTS REPLACEMENT - LIST ITEMS				
S	1	1	FRONT WINDSCREEN CA		\$ 400.0	0	
\$ 625.00 5 1 BONNET HINGE RH \$ \$ 20.00 6 1 BONNET HINGE RH \$ \$ 20.00 7 1 HEADLAMP RH \$ \$ 265.00 8 1 HEADLAMP LOWER BRACKET RH \$ \$ 18.00 9 1 FRONT GRILLE M\$ \$ 145.00 10 1 FRONT GRILLE LOGO KIA M\$ \$ 145.00 11 1 FRONT BUMPER FOG LAMP RH M\$ \$ 290.00 12 1 FRONT BUMPER FOG LAMP COVER RH M\$ \$ 70.00 13 1 FRONT BUMPER FOG LAMP COVER RH M\$ \$ 70.00 14 1 FRONT BUMPER FOG LAMP COVER LH M\$ \$ 70.00 15 1 FRONT BUMPER FOG LAMP COVER LH M\$ \$ 18.00 16 1 FRONT BUMPER SPONGE AT\$ \$ 18.00 17 1 FRONT BUMPER SPONGE AT\$ \$ 10.00 18 1 FRONT BUMPER SIDE RETAINER RH \$ 10.00 19 1 FRONT BUMPER SIDE RETAINER RH \$ 10.00 20 1 FRONT SUPPORT PANEL \$ 10.00 \$ 235.00 \$ 40.00 \$ 30.00 \$ 36.00 \$ 36.00 \$ 36.00 \$ 36.00 \$ 35.00 REPAIR \$ 35.00 REPAIR REPAIR	2	1	FRONT WINDSCREEN MOULDING			0	
\$ 20.00 6 1 BONNET HINGE RH	3	1			\$ 8.00	0	
S		1			\$ 625.00)	
T	5	1	1		\$ 20.00)	
1	6	1	· /		\$ 20.00		
9 1 FRONT GRILLE MIS	7	1			\$ 265.00		
10		1			\$ 18.00		
11					\$ 145.00		
12				·	\$ 35.00		
13					\$ 290.00	l	
14		1		2	\$ 70.00		
15	100				\$ 70.00		
16		1			\$ 18.00		
17		1	1		\$ 18.00		
18		1			\$ 25.00		
19		1			\$ 45.00		
20		1	FRONT BUMPER SIDE RETAINER RH CAL		\$ 10.00		
20		1	FRONT BUMPER SIDE RETAINER LH				
21	20	1		100 mg v			
22	21	1	FRONT BUMPER LOWER LIPS & MUS				
23		1					
24 1 FRONT WIPER MOTOR HOSE (W) \$ 36.00 25 1 FRONT FENDER RH W) \$ 190.00 26 1 FRONT FENDER INNER SHIELD RH (M) \$ 35.00 27 1 FRONT FENDER INNER SHIELD LH (M) \$ 35.00 REPAIR 29 1 FRONT WHEEL HOUSE RH (M) REPAIR 30 1 FRONT PILLAR RH (M) REPAIR 31 1 FRONT DOOR RH (M) REPAIR		1					
25		1					
FRONT FENDER INNER SHIELD RH (**) FRONT FENDER LH ** FRONT FENDER LH ** FRONT FENDER INNER SHIELD LH (**) FRONT FENDER INNER SHIELD LH (**) FRONT WHEEL HOUSE RH (**) FRONT PILLAR RH ** FRONT DOOR RH ** FRONT DOOR RH ** REPAIR REPAIR				4.00			
28 1 FRONT FENDER LH FAPATO 28 1 FRONT FENDER INNER SHIELD LH CAN 29 1 FRONT WHEEL HOUSE RH X 30 1 FRONT PILLAR RH FAPATO 31 1 FRONT DOOR RH FAPATO REPAIR REPAIR REPAIR REPAIR	ì			_			
FRONT FENDER INNER SHIELD LH FRONT WHEEL HOUSE RH FRONT PILLAR RH FRONT PILLAR RH FRONT DOOR RH REPAIR REPAIR	/			2			
29 1 FRONT WHEEL HOUSE RH X 30 1 FRONT PILLAR RH TOUT 31 1 FRONT DOOR RH TOUT REPAIR REPAIR		- 4					
30 1 FRONT PILLAR RH TO REPAIR REPAIR	29	1	FRONT WHEEL HOUSE RH 🖟		33.00		
31 1 FRONT DOOR RH rame	,	1	FRONT PILLAR RH - Gav				
	31	1	FRONT DOOR RH repur		REPAIR		

		ı	1	Ι.	
32	1	FRONT AIR BAG SENSOR RH		\$	66.00
33	1	FRONT AIR BAG SENSOR LH		\$	66.00
34	1	DRIVER SIDE AIR BAG AU		\$	780.00
35	1	AIR BAG CLOCK SPRING	-	\$	110.00
36	1	AIR BAG ECU 🖊		\$	480.00
37	1	FRONT SEAT BELT RH AG		\$	340.00
38	1	CENTRE PILLAR UPPER TRIM RH		\$	40.00
39	1	CENTRE PILLAR LOWER TRIM RH		\$	70.00
40	1	FRONT SEAT BELT LH AG		\$	340.00
41	1	CENTRE PILLAR UPPER TRIM LH	N V	\$	40.00
42	1	CENTRE PILLAR LOWER TRIM LH	1	\$	70.00
43	1	FRONT WHEEL RIM RH		\$	480.00
44	1	FRONT ABSORBER RH 7		\$	150.00
45	1	FRONT ABSORBER MOUNTING RH		\$	48.00
46	1	FRONT KNUCKLE RH ?		\$	160.00
47	1	FRONT KNUCKLE BEARING RH		\$	70.00
48	1	FRONT STABILIZER LINK ROD RH		\$	35.00
49	1	STEERING TIE ROD RH 7	, A	\$	45.00
50	1	STEERING TIE ROD END RH	i e e e e e e e e e e e e e e e e e e e	\$	45.00
51	1	STEERING RACK ?	· · · · · · · · · · · · · · · · · · ·		CHECK PRICES
52	1	FRONT DRIVESHAFT RH		\$	480.00
53	1	FRONT LOWER ARM RH		\$	135.00
54	1	FRONT SUBFRAME ',		\$	550.00
			SUB TOTAL	\$	7,353.00
			MARGIN 10%	\$	735.30
n qu'			TOTAL AMOUNT	\$	8,088.30

Our Ref: SJW7831H

s/NO	QTY	SPECIAL NETT ITEMS	ASSESSED CONDITION	EST. BY WORKSHOP
1	1	FRONT WINDSCREEN SEALANT MA		\$ 80.00
	1	FRONT BUMPER CLIPS		\$ 60.00
2	1	FRONT NUMBER PLATE & HOLDER MIS		\$ 60.00
3	2	FRONT FENDER INNER SHIELD CLIPS RH & LH ^	-/	\$ 50.00
4	1	RADIATOR COOLANT N	r Same a single	\$ 60.00
			SUB TOTAL	\$ 310.00
		Assistant Control of the Control of	TOTAL PARTS COST	\$ 8,398.30

Our Ref: SJW7831H

S/NO	DESCRIPTION	EST. BY W	VORKSHOP		
	LABOUR & PAINTW	/ORK			
1	REMOVE, REFIX AND REPAIR AFFECT	TED DAMAGED PARTS	\$	1,000.00	
2	TO REMOVE & REFIT FRONT	\$	120.00		
3	SIMPLE WIRING	\$	20.00		
4	TO REMOVE & REFIT AIR CON CONDENSER, I	\$	100.60		
5		ANTI RUST COATING			
6	PAINT MATERIALS PER	PAINT MATERIALS PER PANEL			
7	SUNDRIES		\$	1,200.00 3 C	
1 1 1 1 1 1 1		TOTAL BEFORE GST	\$	10,948.30	
		LESS EXCESS	\$	-	
		TOTAL BEFORE GST	\$	10,948.30	
		7% GST	\$	766.38	
		TOTAL REPAIR COST	\$	11,714.68	

Adjustments / Recommendations

Our estimator have throughly inspected each and every item on the estimate against physical damage found on the vehicle and have listed the breakdown of our finding and recommendation.

**This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

***On a separate note, please let us have your authorize repair confirmation and/or approval for the above OD case in your next reply.

Yours Faithfully,

Jason Heng **Claims Director**

> LKK Auto Consultants hence notify the Repairer of the following:

- · To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- · No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Resus after report

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver

Vehicle Registration Number

- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for Investigation.

- 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/01/2022 15:58 (SGT)
Date of Accident	18/01/2022 22:30 (SGT)
Exact Location of Accident	Tuas South Ave 6, Singapore
Additional Location Information	- 1
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

SJW7831H

INSURED/POLICYHOLDER	
Is company? Name Of Registered Owner Company Reg No	Yes STK METAL & LEATHER PTE LTD 2XXXXX279F

 Company Reg No
 2XXXXX279E

 Email Address
 stkmlsg@gmail.com

 Mobile Phone No
 (Phone) +65-63860669

 Alternative Phone No
 (Office) +65-63860669

VEHICLE PARTICULARS

Manufacturer	Kia	
Model	Cerato	
Variant	Cerato	
Exact purpose for which vehicle was being used at time of	-	
accident	Private use	
Are you claiming under your own insurance policy for repair to		
your vehicle?	Yes	
Vehicle Category	Private car	
Transmission	Auto	
CC	1591	

INSURANCE COMPANY

Fleet Policy	Allianz Insurance Singapore Pte. Ltd. Comprehensive No
Policy Number Cover Note Number	SP2000589680-01

Of Birth upation e Of Driving Pass ving experience ender Nobile Number Alt. Phone Number Email Address Address Address Address complement Postcode Is the driver the policyholder? If No, Relationship of the Driver with the Insured Does Driver Own Other Vehicles? Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver	Indoor 06/11/2012 9 YEARS AND 2 MONTHS Male (Phone) +65-91237949 - stkmlsg@gmail.com BLK 103 TAMPINES ST 86 #03-06 - 528576 No OWNER Yes
GENERAL INFORMATION OF THE ACCIDENT	
Type of Accident Weather Conditions Road Surface	Collision - Head on collision Clear Dry
OTHER INFORMATION	
Was any foreign vehicle involved in the accident? Number of vehicles involved in the accident Was anybody injured in the Accident? Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Number of Passengers (Including Driver) Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No 1 No - No 1 No
DETAILS OF POLICE ACTION	
Was the accident reported to the police? Was notice of intended Prosecution given? If yes, against whom? CIRCUMSTANCES OF ACCIDENT	No No
REFER SKETCH.	
ATTACHMENT(S)	
Are accident photos available for attachment? Was there any video captured by Car Camera? Was there any audio recorded?	Yes No No

LM	vas c	drive	the	ar	fra	10/4	r fn	owe .	Tuas	vie	V (1n	c +	6_7	bas	Sou
eb	, a	ton	-tn	ick	park	bes	ide -	the	road	1	-Coton				
he	Arm	k an	- A		cond										
4, 2	A CONTRACTOR OF THE PARTY OF TH	And the second		300	No.		-	The second secon	y y	- me					
-	- Washington				A Section of the sect		4						A		
	4				1971	A.C		****			N I			The second	
			A										-	10	
		N Tonga	32-2-3												
4 7)				And the state of t											
				The second second				Taylor .						-	
					- American		2 1 -42	***				-3-			
				and a	1 2 2 2 2 2		Address of	Surviva -	pt some						-
-		A Survey of the	77 77	- Special Control	- 31	100	N. Committee		c =-,			- N-1-	-		
		Total State of the	1 - 12 min			1 mm y 10		-	. 5.00				- 1	-	-
	(p)		. 3 - 3 -	(mary manager)				Total and the	The second second		2 -201-	7			
CONTRACTOR			A same of			-									
5 5				-31 Mg	w			. K							
Z. Prof.	-W 1 W			id Solution		American Company					may have		-		1
						aktivija.		F 71063	1					o. he.	
						73		- 1							e .
			-14 10-				Topics Service Service					- 12. J			
		the second secon		A. C.				DrU	The Name of Street, St					, Name	
2012 <u></u>				April April 2	-6-			Pro							
		***************************************	1	The second second				(Selection)	300	- \.	North Co	All many		-	

Declaration

I'Ve ductore the to config particulars are true in every respect.

Policyholder's Signature / Date & Time Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre-Personnel Allianz Insurance Singapore Pte, Ltd.

Company Registration No.: 201903913C GST Registration No.: 201903913C

Address: 79 Robinson Road #09-01 Singapore 088897

Tel: +65 6714 3369 Website www.allianz.so

Allianz Contact Centre Tel: 1800 222 1818 (Local) +65 6222 1919 (Overseas)

Email: customerservice@allianz.com.sq.

Allianz (II)

CERTIFICATE OF INSURANCE

FORM

MX4

ROAD TRANSPORT ACT 1967 (MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS) RULES 1959 (FEDERATION OF MALAYSIA)

MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) ACT (CAP 188 OF THE REVISED EDITION) (BEPUBLIC OF SINGAPORE)
MOTOR VEHICLES (THIRD-PARTY RISKS AND COMPENSATION) AULES 1898 (REPUBLIC OF SINGAPORE)

OR ANY AMENDMENT, ACT OR ACTS PASSED IN SUBSTITUTION THEREOF

Certificate Number

: SP2000589680-01

Coverage

: COMPREHENSIVE

Policyholder Name

: STK MEYAL & LEATHER PTELTD

Registration No.

1 S.M7831H

Period of insurance

: 19 OCTOBER 2021 to 18 OCTOBER 2022

Persons or Classes of Persons Entitled to Drive":

The Policyholder. (30)

(0) Any other person who is driving on the Policyholder's order or with the his/her permission

*Provided that the person driving is permitted in accordance with the licensing or other laws or regulation to drive the Motor Vehicle or has been permitted and is not disqualified by order of Court of Law or by reason of any enactment or regulations in that behalf from driving the Motor Vehicle. And provided further that the Motor Vehicle is registered under the Road Treffic Act has not been cancelled at the time of accident loss or damage.

Limitation as to Usa":

Used only for social, domestic and pleasure purposes and for the Policyholder's business.

The Policy does not cover:

- (a) use for hire or reward
- (b) use for racing, pace-making, reliability trials or speed testing
- use for the certiage of goods (other than samples) in connection with any trade or business
- (d) use for any purposes in connection with the Motor Trade

Limitation rendered inoperative by Section 8 of Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act, 1987 (Malaysia), are not to be included under these headings.

IWE HEREBY CERTIFY that the Policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia) or Amendment, Act or Acts passed in substitution thereof

Allianz Insurance Singapore Pts. Ltd.

16 October 2021

Issued Date

Hicham Raisal Chief Executive Officer Allianz Insurance Singapore Pte. Ltd.

Account Code: 0000237

Excess:

Own Damage Excess Windscreen Excess

SGD

600 00

SCD

100.00

SKETCH PLAN

IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Formmust be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association
- of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- B. Consent under the Personal Data Protection Act (PDPA)

l understand, acknowledge, agree and consent that :

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the 'Personal Information') and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the 'Insurers'), the insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims:
- (ii) Investigating the accident and/or my claims.
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims. (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the insurers' law yers/law firms, may/are permitted to collect. use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature

Exiver's Signature (If driver is not the policyholder) / Date

& Time

Witnessed by Reporting Centre Personnel

Sketch Plan

Tuai South Ave 6

AISJW1831H

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Owner ID Type:	Company
Owner ID: Vehicle Details	279E
Vehicle No.:	SJW7831H
Vehicle to be Exported:	No.
ntended Deregistration Date:	21 Jan 2022
Vehicle Make:	KIA
Vehicle Model:	CERATO EX FORTE 1.6L A/T ABS AB 2WD 4DR
Primary Colour:	Black
Manufacturing Year:	2010
Engine No.:	G4FCAH362993
Chassis No.:	KNAFU411MA5200352
Maximum Power Output:	92.7 kW (124 bhp)
Open Market Value:	\$11,398.00
Original Registration Date:	19 Apr 2010
First Registration Date:	19 Apr 2010
Transfer Count:	3
Actual ARF Paid: Intended PARF Rebate Details	\$11,398.00
PARF Eligibility:	Forfeited
PARF Eligibility Expiry Date:	
PARF Rebate Amount: Intended COE Rebate Details	\$0.00
COE Expiry Date:	18 Apr 2025
COE Category:	A - Car (1600cc & below)
COE Period(Years):	5
PQP Paid:	\$16,438.00
COE Rebate Amount:	\$10,663.00
Total Rebate Amount: Message	\$10,663.00 be further renewed. The vehicle must be de-registered upon COE expiry or when the

The information contained herein is correct as at 21 Jan 2022