

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	ALLIANZ INSURAN	NCE SINGAPORE PTE LTD	Ref:	CS/AIS22000803/Kvf3n2	
	79 ROBINSON RO #09-01 SINGAPOR		Date	24/05/2022	
			Code	: AIS	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SMD 2631R	Veh. Inspected	SCY 3838M	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	2022 22003808/FQ	Excess (\$)	0.00	
	Assign From	SHANTI	Assign Date	24/01/2022	
2. Vehicle Particulars & Condition					
	Make & Model	HONDA CIVIC (A)	c.c	1498	
	Engine No.	HIDDEN	Year of Reg.	2017	
	Chassis No.	MRHFC1660HT000392	Colour	METALLIC BLUE	
	Odometer	59626 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	235/40 R18	GOODYEAR	7 mm	
	L/H Front Tyre	235/40 R18	GOODYEAR	7 mm	
	R/H Rear Tyre	235/40 R18	GOODYEAR	7 mm	
	L/H Rear Tyre	235/40 R18	GOODYEAR	7 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S AND FRONT N/S PORTION.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	23/01/2022	Inspection Date	24/01/2022	
	Survey held at	Survey held at BLK 01 SIN MING INDUSTRIAL SECTOR C #01-135. Repairer A T AUTO CONSULTANT			
	Repairer				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days				
	•				