

FASTECH AUTO PTE LTD

1 Kaki Bukit Ave 6 #01-48 Autobay

Singapore 417883

Tel No: 67452063/ 67467158 Fax No: 67458520

Tax Reg No : 200006262D

Hiary Tony

not Arthur
24/1/22
1/5 \$6000
4 days

VEHICLE No: SLF 6215J

1PC	REAR WINDSCREEN MOULDING	11	\$110.20	X
1PC	REAR FENDER N/S	R	\$971.10	X
1PC	REAR DOOR N/S	Body RD	1198.10	\$1,255.10
1SET	REAR DOOR FRAME BLACK STICKER N/S	nee	65.00	\$85.00
1PC	REAR DOOR GLASS OUTER CHROME N/S	nee		\$168.20
1PC	REAR DOOR GLASS REGULATOR N/S	Beif	322.50	\$399.00
1PC	REAR DOOR GLASS REGULATOR MOTOR N/S	shorted	280.10	\$650.00
1PC	REAR DOOR INNER LOCK N/S	SWC		\$392.20
2PCS	REAR DOOR HINGES N/S @\$80.00	Top SWC		\$160.00
1PC	REAR DOOR CHECKER N/S	SWC		\$121.00
1PC	REAR DOOR INNER RUBBER N/S	nee		\$198.80
1PC	REAR DOOR INNER TRIM BOARD N/S	De/Torn	600.10	\$971.30
1PC	FRONT DOOR N/S	Body RD	1298.10	\$1,355.10
1SET	FRONT DOOR FRAME BLACK STICKER N/S	nee	65.00	\$85.00
1PC	FRONT DOOR GLASS OUTER CHROME N/S	nee		\$168.10
1PC	FRONT DOOR GLASS REGULATOR N/S	Beif		\$355.00
1PC	FRONT DOOR GLASS REGULATOR MOTOR N/S	shorted	280.10	\$650.00
1PC	FRONT DOOR INNER LOCK N/S	SWC		\$392.20
1PC	FRONT DOOR INNER TRIM BOARD N/S	De/Torn	681.10	\$950.10
1PC	FRONT DOOR INNER RUBBER N/S	nee	182.50	\$195.10
2PCS	FRONT DOOR HINGES N/S @\$80.00	Top Beif		\$160.00
1PC	FRONT DOOR CHECKER N/S	SWC		\$121.00
1PC	CENTRE PILLAR N/S	R		\$699.20
1PC	FRONT FENDER N/S	DD	648.20	\$655.10
1PC	FRONT FENDER 'VVTI' EMBLEM N/S	nee	68.10	\$85.00
1PC	FRONT FENDER INNER SHIELD N/S	11		\$198.10
1PC	FRONT FENDER INNER SHIELD CLIPS N/S	11		\$50.00
			\$11,600.90	

S.NETT ITEM

1PC	FRONT SPORT RIM N/S	11	\$850.00	X
1SET	DOOR VISOR N/S	nee	\$150.00	60
1PC	REAR WINDSCREEN SEALANT	11	\$50.00	X
1PC	REAR WINDSCREEN INNER SEAL	11	\$50.00	X
TO CHECK WIRING			\$50.00	20
TO DISMANTLE & REFIX REAR REVERSE SENSOR			\$80.00	40
TO DISMANTLE & REFIX REAR WINDSCREEN			\$120.00	X
TO TRANSFER BOTH N/S DOOR MECHANISM			\$150.00	100

TO DISMANTLE & REFIX SEAT CUSHION UPHOLSTERY
 TO DISMANTLE & REFIX FUEL TANK
 TO CONDUCT WHEEL ALIGNMENT
 LABOUR FOR PANEL BEATING & REPLACED PARTS
 TO PUTTY & SPRAY PAINTING

	\$120.00	60
11	\$100.00	X
	\$120.00	60
	\$1,200.00	600
	\$1,680.00	1000
TOTAL	\$16,320.90	

LKK Auto Consultants hence notify
 the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-7457
 252
 95592.75
 S.N-60
 2-1880
 7532.75
 6026