

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	SURANCE (S) PTE LTD		Ref:	CS/CTI22000841/Ety3	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909		Date:	24/01/2022	
				Code:	СТІ	
1. Policy Particulars :- THIRD PARTY CLAIM						
	Insured Veh.	SGJ 2594D	Veh. Inspected		GBH 6062R	
	Policy No.	DMPCSNW00118072103	Coverage (\$)		0.00	
	Claim No.	SNM22D200541/C02/SGJ2594 D/THAMYL	Excess (\$)		0.00	
	Assign From	PAULINE THAM	Assign Date		24/01/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	Steering				
	Brakes	Modification				
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4.	Description of Damages					
5. General Information						
	Accident Date	21/01/2022	Inspection Date	е	28/02/2022	
	Survey held at	vey held at SNG AH TEE MOTOR & PANEL SERVICE PTE LTD				
		BLK 3, PIONEER ROAD NORTH, #01-18 SINGAPORE 628457.				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					