



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
ALLIANZ INSURANCE SINGAPORE PTE LTD 79 ROBINSON ROAD #09-01 SINGAPORE 068897			Ref: CS/AIS22000851/Etf3n2	
			Date: 25/03/2022	
			Code: AIS	
1. Policy Particulars :- OWN DAMAGE				
	Insured Veh.		Veh. Inspected	SMD 2631R
	Policy No.	SP2000439978	Coverage (\$)	0.00
	Claim No.	2022 22003808	Excess (\$)	600.00
	Assign From	SHANTI	Assign Date	25/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A5	c.c	1984
	Engine No.	HIDDEN	Year of Reg.	2018
	Chassis No.	WAUZZZF54JA098351	Colour	RED
	Odometer	26435 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	275/30 R20	FALKEN	5 mm
	L/H Front Tyre	275/30 R20	FALKEN	5 mm
	R/H Rear Tyre	275/30 R20	FALKEN	5 mm
	L/H Rear Tyre	275/30 R20	FALKEN	5 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	23/01/2022	Inspection Date	26/01/2022
	Survey held at	24 BENOI SECTOR SINGAPORE 629857		
	Repairer	PREMIUM AUTOMOBILES PTE LTD		
5a. Remarks				
	A)THE MARKET VALUE IS S\$145,000.00 (EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		9 Working Days	