COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Effective Date: 1 Nov 2020

DATE:

19-Jan-22

MODEL:

Hyundai loniq

VEHICLE NO .:

SHD6886E

INSURANCE: CHINA TAIPING (P)

MVA: LIM TS

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT	
	Rear Bumper	1		\$459.40	-
	Rear Bumper Reinforcement	1		\$394.80 7. 1	Cinc
	Rear Bumper Reinforcement Bracket RH/LH	2	\$138.10	\$276.20 7.	KSVC
	Rear Bumper Centre Moulding Assy	1		\$451.25 / \$	cr
	Rear Bumper Lower Centre Moulding Assy	1		\$155.00 %	10
	Rear Bumper Cover Clips	10	\$2.20	\$22.00/1100	6
	Rear Bumper Tow Cover	1		\$98.80 XSU	IC
	SUB TOTAL			\$1,857.45	
	LESS 20%			\$371.49	
	DISCOUNTED TOTAL			\$1,485.96	
	Rear Bumper Mat	1		\$50.00 × 5	ive
	Rear Bumper Reverse Sensor	1		\$180.00	cuf
	Treat Bamper Neverse Consor	'		7	
	S/NETT TOTAL			\$230.00	
	SPARE PARTS TOTAL			\$1,715.96	
	Labour Charge				
	Panel Beating				350
	Spray Painting Charge				250
	Remove/Refix Reverse Sensor			\$120.00	30
	TOTAL LABOUR			\$820.00	
	ESTIMATE TOTAL			\$2,535.96	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Thevan @ Chhauto lom 87235769 19/1122 14600 19/19 birpaint photo 2 clays wp

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: