

T & B MOTOR REPAIRS SERVICES PTE LTD

10 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

MR GIONG CHUN WEE

Not Authorized
11 Pk @ 5400k
Resurvey After Paint
4 days

Estimate : ES003453

Attention : Motor Claim Department

Date : 24/01/2022
Vehicle Num. : SJH7749S
Make/Model : TOYOTA ALLION 1.5A
Chassis/Eng# :
Accident Date : 23/01/2022
Claim No. :
Reference :
Policy No. : GA575802/1

S/N Quantity Particular Unit Price Amount S\$

S/N	Quantity	Particular	Unit Price	Amount S\$
LIST ITEMS :				
1.	1	FRONT FENDER R/H <i>553.20</i>		966.85
2.	1	FRONT FENDER INNER SHIELD RH		298.25
3.	10	FRONT FENDER INNER SHIELD CLIP RH	6.50	65.00
4.	1 (SIDE)	FRONT FENDER INNER BRACKET L/H		80.40
5.	1	FRONT HEAD LAMP R/H		1,030.20
6.	1	FRONT GRILLE		390.70
7.	4	FRONT GRILLE CLIPS	6.50	26.00
8.	1	FRONT BUMPER <i>102040</i>		1,132.95
9.	1	FRONT BUMPER SIDE RETAINER RH		80.35
10.	1	FRONT BUMPER SIDE RETAINER LH		80.35
11.	1	FRONT BONNET <i>916.20</i>		1,227.20
12.	1	FRONT SUPPORT PANEL <i>744.60</i>		1,219.70
13.	1	FRONT SHOCK ABSORBER RH <i>368.80</i>		680.90
14.	1	FRONT SHOCK ABSORBER TOP MOUNTING RH		130.20
15.	1	FRONT LOWER ARM RH <i>419.70</i>		510.15
16.	1	FRONT LOWER ARM BALL JOINT		141.40
17.	1 (R/H)	FRONT WHEEL KNUCKLE ARM		381.25
18.	1	FRONT WHEEL HUB BEARING ASSY R/H		149.30
19.	1	FRONT TYRE RH		320.00
20.	1	FRONT SPORT RIM RH		500.00

List Total S\$:

25.00% Discount S\$:

9,411.15

2,352.79

7,058.36

LABOUR :

1. CHECK & REPAIR WIRING

2. COMPUTER ALIGNMENT

120.00

120.00

CONTINUE / ...

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

20k
60k

T & B MOTOR REPAIRS SERVICES PTE LTD

50 SIN MING DRIVE #08-03 SIN MING AUTOCITY SINGAPORE 575722

Tel No. : 6458 0296 / 6454 8007 Fax No. : 6554 2640

E-Mail : tbmotor@hotmail.sg

Buss. Reg. No. : 199001597D

WITHOUT PREJUDICE

MR GIONG CHUN WEE

Estimate : ES003453

Date : 24/01/2022

Vehicle Num. : SJH7749S

Make/Model : TOYOTA ALLION 1.5A

Chassis/Eng# :

Accident Date : 23/01/2022

Claim No. :

Reference :

Policy No. : GA575802/1

Attention : Motor Claim Department

S/N	Quantity	Particular	Unit Price	Amount S\$
		3. TYRE HIGH SPEED BALANNING		80.00
		4. SPRAY PAINT ANTI-RUST COATING		180.00
		5. DISMANTLE AND FIX BACK UNDERCARRIAGE		480.00
		6. SPRAY PAINTING		1,200.00
		7. LABOUR TO DO PANEL BEATING		1,200.00
		Labour Total S\$:		3,380.00

15L
60L
280L
880L
600

SingDollars : Ten Thousand Four Hundred Thirty-Eight & Cents Thirty-Six Only

E. & O.E.

Total S\$: 10,438.36

=====

for T & B MOTOR REPAIRS SERVICES PTE LTD