



38, Woodlands Industrial Park E-1, #01-16, Singapore 757700
Tel : 6468 1322 Fax : 6468 1376
Email : mohdauto@yahoo.com
Reg No : 53326419 K

To: ALLIANZ Insurance

24th January 2022

Attn : Motor Property Claims

Dear Sir,

Accident Involving SGX-9423-U & SJH-2555-S (23rd Jan 2022)


Quotation for the repair of vehicle number SGX-9423-U

No	Description	Price
1	1 Piece Rear Bumper <i>de</i>	\$ 780.00
2	2 Pieces Rear Bumper Side Retainers <i>ne</i>	\$ 78.00
3	2 Pieces Rear Bumper Clips <i>ne</i>	\$ 12.00
4	2 Pieces Rear Bumper Reflectors <i>Xnn</i>	\$ 85.00 X
5	1 Piece Rear Boot <i>bt</i>	\$ 580.00
6	2 Pieces Rear Boot Hinge <i>Xnn</i>	\$ 130.00 X
5	1 Piece Rear Panel Garnish <i>cm</i> 2695	\$ 120.00
6	2 Pieces Rear Panel Clips <i>ne</i> 2590	\$ 15.00
7	2 Pieces Tail Lamp <i>cm</i> 2021.25	\$ 660.00
8	2 Pieces Clips <i>ne</i>	\$ 15.00
9	1 Piece Rear Boot Rubber <i>ne</i>	\$ 130.00
10	1 Piece Rear Boot Lock <i>cut</i>	\$ 160.00
11	1 Piece Rear Boot Latch <i>bt</i>	\$ 85.00
12	1 Piece Spare Tyre Sponge (RH) <i>cm</i>	\$ 60.00
13	1 Piece Spare Tyre Sponge (LH) <i>Xnn</i>	\$ 60.00 X
14	1 Piece Panel Sealant <i>ne</i>	\$ 100.00 60 s/n
15	2 Pieces Reverse Sensor <i>new</i>	\$ 300.00 200 s/n
Total		\$ 3370.00
Less 25 %		\$ 842.50
Total		\$ 2527.50 260

1	Labor Charge Rear Panel Beating	\$ 490.00	450
2	Spray Painting	\$ 550.00	500
3	Rust Proofing	\$ 120.00	60
4	Number of repair days (50.00 x 6 days)	\$ 300.00	?
Total		\$ 3987.00	1010

In Singapore Dollars: THREE THOUSAND, NINE HUNDRED AND EIGHTY SEVEN DOLLARS ONLY

Mohamed Automobile



Ameer Ali

9387-8260

Mohdanto@yahoo.com

2021.25

260.00

1010.00

3291.25

20%

2633

4/5- \$2,600

Rasul

Hp 90010068

6 days

4/5

25/01/22 @ 1510

Rasul after repair

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: