

Veron Chen (LKKAuto)

From: Admin-D (LKKAuto)
Sent: Thursday, 27 January 2022 5:33 PM
To: Veron Chen (LKKAuto)
Subject: FW: PC7674D and SMD7120R DOA 21.1. 22
Attachments: PC7674D and SMD7120R DOA 21.1. 22.pdf; TP vehicle SMD7120R DOA 21.1. 22.pdf

Best Regards,

Summer Lee | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

Note: We are on work from home arrangement. All correspondence should be made via email. Submission of claim related documents will be in softcopy. Any inconvenience caused is much regretted.

From: Olivia Lau (LKKAuto) <olivialau@lkkauto.com>
Sent: Thursday, 27 January, 2022 5:21 PM
To: Hsiao Tong (LKKAuto) <chewht@lkkauto.com>; assignments <assignments@lkkauto.com>; Admin A <admin-a@lkkauto.com>
Subject: FW: PC7674D and SMD7120R DOA 21.1. 22

From: Mekavathanan Sarangapani <mekavathanan@iii.com.sg>
Sent: Thursday, 27 January 2022 5:20:36 pm (UTC+08:00) Kuala Lumpur, Singapore
To: Dhanya B.Purushothaman <Dhanya@iii.com.sg>; KKLau <kklau@lkkauto.com>; Olivia Lau (LKKAuto) <olivialau@lkkauto.com>; Hsiao Tong (LKKAuto) <chewht@lkkauto.com>
Subject: PC7674D and SMD7120R DOA 21.1. 22

Dear LKK team

Do we have CCTV footages from respective vehicles - have we asked for the same yet ?

A: TP's version :

RELEVANT CIRCUMSTANCES OF THE ACCIDENT

on 21 Jan 2022 at about 18:25 I was driving along
1. BIK 134 Jurong East central to ward Jurong Town Hall.
I was driving at lane two. The Bus PC7674D came out
from the Bus stop and hit my left door and lost control
and stop. I and my husband came down and check our
car. The damage is bad. We waited for TP and Tow to
Come.

Brief Details

On 21.01.2022 at about 1830hrs I was driving along the said location at the right side of a two lane road. I then noticed a SBS bus on the left side of the road. I proceeded to signal and drive to the left lane however the SBS bus did not give way and eventually collided with my vehicle head to side. The impact of the collision led my vehicle to swerve sideways. There was only police at scene however no ambulance. My husband who was the passenger then suffered abrasion on his right shoulder however have not seek medical attention.

The damage of my vehicle is as follows

1. Left rear door unable to open and scratched
2. Left front bumper crashed
3. Left front boot cracked
4. Left side of the windscreen cracked
5. Vehicle registration plate dismantled
6. Airbag burst and engine oil leaked

ATTACHMENT(S)

- Are accident photos available for attachment?
- Was there any video captured by Car Camera?
- Reasons for not uploading a video of the accident
- Was there any audio recorded?



Main | Offer Processing | Cla


CLAIM SUBFOLDER DETAILS

Insured:	
Main Claimant:	-
Vehicle Reg. No.:	SMD7120R
Claim Type:	TP ... [MRMCaseID: SG1063792]
Vehicle Reg. No. (Insured):	PC7674D
Repairer:	SPEEDWERKZ PTE LTD (HQ) PROFILE 13 Kaki Bukit Road 4, #01-20 Bartley Biz Centre, 14780
Handling Insurer:	India International Insurance Pte Ltd (HQ) - Tel: 63476100 ... [Handled by Bhargavi Purush
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Thevan Thomas Karthik
Init. Est. Repair Costs:	5,000 - 6,000

B : Insured - Insured has CCTV footage :







DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

21/1/2022 下午 18:17 分在 禧街 对 右 边 有 个 弯 道 情 况 下 撞 到
 先 自 右 前 边 说 话 对 方 车 辆 转 弯 撞 上 我 的 右 边
 在

Translate:

21/1/22 afternoon 1817 at Jurong East Central the other party without safety measure collided onto my bus front right and turn and hit my left side.

Best Regards,

Mekavathanan
HOD
Motor & Work Injury Claims Department
India International Insurance Pte Ltd
64 Cecil Street, #04/#05 IOB Building, Singapore 049711
DID: 6347 6105 Fax: 6224 4174



Scan to pay now. UEN: 198703792KSIF



This email is intended solely for the person to whom it has been addressed. It may contain confidential and/or legally privileged information. If you are not the person for whom this e-mail was intended, or if this e-mail has reached you by mistake, please delete it immediately and inform us of the error and also be hereby notified that any use, distribution, transmission, printing, copying or dissemination of this information in any way or in any manner is strictly prohibited and may be unlawful. Internet communications may not be entirely secure or accurate as

information could be intercepted, corrupted, lost, delayed or contain viruses. Therefore, we do not accept liability for any errors or omissions in the content of this message or any delay in delivery which may arise as a result of Internet transmission or any modification. If you have sent or are sending personal data, you undertake that the personal data being sent is current, complete and accurate. You understand and consent that the personal data may be processed and retained by India International Insurance Pte Ltd (“III”) in line with the purposes in III’s Personal Data Policy (<https://www.iii.com.sg/privacy-policy>). For third party’s personal data, you undertake that you have obtained the consent from the third party and made the party aware of all matters listed in this policy by referring them to III’s website. This message may contain confidential information intended only for the individual named. If you are not the named addressee, do not disseminate, distribute or copy this email. Please notify the sender immediately and delete this email from your system. Any views expressed in the email are those of the individual sender, except where the sender specifically states them to be the view of III. The information and/or comments provided or expressed in this message are not to be construed as legal advice and are not intended to replace legal advice. You should not rely on any information and/or comments provided or expressed in this message/research memorandum as legal advice. III shall not be responsible for any loss or damage arising from your reliance on any information and/or comments provided or expressed in this message.”