



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

PRE-REPAIR INSPECTION REPORT				
AXA INSURANCE PTE LTD 8 SHENTON WAY #24-01 AXA TOWER SINGAPORE 068811 ATTN: KOH JANICE			Ref: CS3/ASM22000900/Ety3e2 Date: 11/02/2022 Code: ASM	
1. Policy Particulars :- (THIRD PARTY CLAIM)				
	Insured Veh.	EK 9988Z	Veh. Inspected	FBR 7104U
	Policy No.	GA568525	Coverage (\$)	0.00
	Claim No.	S2M03RJQ	Excess (\$)	0.00
	Assign From	KOH JANICE	Assign Date	25/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA ADV150A	c.c	149
	Engine No.	HIDDEN	Year of Reg.	2020
	Chassis No.	KF381007150	Colour	BLACK
	Odometer	-	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	110/80-14	GOODYEAR	4 mm
	L/H Front Tyre			mm
	R/H Rear Tyre	130/70-13	GOODYEAR	4 mm
	L/H Rear Tyre			mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.			
5. General Information				
	Accident Date	17/01/2022	Inspect Date / Time	26/01/2022 (12:17 PM)
	Survey held at	BIKERS AVENUE PTE LTD NO 1 BUKIT BATOK CRESCENT #02-58 WCEGA PLAZA SINGAPORE 658064		
5a. Remarks				
	A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS. D) THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$2,000-\$3,000			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	

Report Ref No. CS3/ASM22000900/Ety3e2

Inspected By



CHEN TSUE YEE

Automotive Assessor



K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE, MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.