

Submit to insurance.

not Anthony
dele

10/1/22

1/5 \$4800

3 days

SND347M Volkswagen Passat

No	Qty	Part				
1	1	Front bumper assy	2/02	1592.85	\$	1,606.00 ✓
2	1	Front bonnet assy	11		\$	2,620.00 X
3	1	Front bumper sponge	10/11	164.20	\$	186.00 ✓
4	2	Front bumper retainer	11		\$	167.00 X
5	2	Front bumper bracket	11		\$	186.00 X
6	2	Front support panel side garnish	11		\$	95.00 X
7	1	Front bumper top beam	11		\$	388.00 X
8	1	Front bumper reinforcement	10		\$	579.00 ✓
9	1	Front bonnet lock mechanism	11		\$	298.00 X
10	1	Front bumper lower grille	10/11	245.00	\$	399.00 ✓
11	1	Front bumper lower grille upper chrome moulding	11		\$	197.00 X
12	1	Front bumper lower grille lower chrome moulding	10/11		\$	227.00 ✓
13	1	Front bumper lower grille left side chrome moulding	11		\$	129.00 X
14	1	Front bumper lower grille right side chrome moulding	11		\$	129.00 X
15	1	Front bumper right day lamp	11		\$	353.00 X
16	1	Front bumper right day lamp garnish	11		\$	156.00 X
17	1	Front bumper right day lamp garnish chrome moulding	11		\$	95.00 X
18	1	Front bumper lower engine cover	10/11	341.10	\$	765.00 ✓
19	1	Front grille assy	10/11		\$	607.00 ✓
20	1	Front grille top chrome moulding	10/11		\$	363.00 X
21	1	Front grille centre lgo	11		\$	128.00 X
22	1	Front right LED headlamp	10/11	2166.00	\$	3,060.00 ✓
23	1	Front right LED headlamp top chrome moulding	11		\$	271.00 X
24	1	Front tow cover	11		\$	88.00 X
25	1	Front right headlamp spray nozzle cover	11		\$	95.00 X
26	1	Front right headlamp spray nozzle	11		\$	395.00 X
					\$	13,582.00
Less 10%					\$	1,358.20
					\$	12,223.80

Special Nett Items

1	16	Front bumper clips	10/11		\$	60.00 50 s/n
2	6	Front grille clips	11		\$	50.00 X
3	10	Front bumper lower grille clips	11		\$	40.00 X
4	4	Front bumper parking sensor	10/11		\$	1,200.00 X
5	20	Front bumper lower engine cover clips	11		\$	80.00 X
6	1	Front no plate with garnish	10/11		\$	200.00 80 s/n
					\$	1,630.00

Total parts

\$ 13,853.80

SND347M Volkswagen Passat

No			
1	Labour for panel beating, cut, weld, straighten front affected area and replace front damaged parts.	\$ 1,200.00	300
2	To putty and spray painting front portion.	\$ 1,200.00	280
3	To check wiring and focus front headlamp.	\$ 60.00	20
4	To remove and install front bonnet lock mechanism.	\$ 1180.00	X
5	To remove and install air con system to facilitate the repair and refill gas.	\$ 11150.00	X
6	To remove and install cooling system to facilitate the repair and check for leakage.	\$ 11150.00	X
7	To apply anti rust proofing to front affected area.	\$ 11140.00	X
8	Towing service.	\$ 11100.00	X
Total labour :		\$ 3,080.00	

Total parts : \$ 13,853.80
Total labour : \$ 3,080.00
Total repair cost : \$ 16,933.80

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

P-5256.15
 102
 P-5270.53
 S.N-130
 L-600
 6000.53
 202
 4800