

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	CHINA TAIPING IN	ISURANCE (S) PTE LTD		Ref:	CS/CTI22000924/Kty3	
	3 ANSON ROAD # SPRINGLEAF TOV	16-00 VERSINGAPORE 079909		Date:	26/01/2022	
				Code:	СТІ	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SJN 3431C	Veh. Inspected		SLK 5432D	
	Policy No.	DMPCSNW00023072200	Coverage (\$)		0.00	
	Claim No.	SNM22D200620/C02/SJN3431 C/THAMYL	Excess (\$)		0.00	
	Assign From	PAULINE THAM	Assign Date		26/01/2022	
2. Vehicle Particulars & Condition						
	Make & Model		c.c		0	
	Engine No.	HIDDEN	Year of Reg.			
	Chassis No.		Colour			
	Odometer	-	Steering			
	Brakes		Modification			
	General					
3. Conditions of Tyres						
		Size	Make		Balance	
	R/H Front Tyre				mm	
	L/H Front Tyre				mm	
	R/H Rear Tyre				mm	
	L/H Rear Tyre				mm	
4. Description of Damages						
5. General Information						
	Accident Date	20/01/2022	Inspection Dat	е	28/01/2022	
	Survey held at	AH LIM MOTOR COMPANY				
		NO 10 ANG MO KIO IND PK 2A #01-09 AMK AUTOPOINT SINGAPORE 568047				
5a. Remarks						
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					