



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | |
|---|--|--|--|------------|
| STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705 | | | Ref: CS/SMR22000941/c Date: 26/01/2022 Code: SMR | |
| 1. Policy Particulars :- THIRD PARTY CLAIM | | | | |
| | Insured Veh. | SG 5960J | Veh. Inspected | SKW 7590R |
| | Policy No. | | Coverage (\$) | 0.00 |
| | Claim No. | | Excess (\$) | 0.00 |
| | Assign From | HUA YEN | Assign Date | 26/01/2022 |
| 2. Vehicle Particulars & Condition | | | | |
| | Make & Model | | c.c | 0 |
| | Engine No. | HIDDEN | Year of Reg. | |
| | Chassis No. | | Colour | |
| | Odometer | - | Steering | |
| | Brakes | | Modification | |
| | General | | | |
| 3. Conditions of Tyres | | | | |
| | | Size | Make | Balance |
| | R/H Front Tyre | | | mm |
| | L/H Front Tyre | | | mm |
| | R/H Rear Tyre | | | mm |
| | L/H Rear Tyre | | | mm |
| 4. Description of Damages | | | | |
| | | | | |
| 5. General Information | | | | |
| | Accident Date | 24/01/2022 | Inspection Date | |
| | Survey held at | BORNEO MOTORS (S) PTE LTD 2 PANDAN CRESCENT SINGAPORE 128462 | | |
| 5a. Remarks | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | |