



GOLDBELL ENGINEERING

Industrial Vehicles.
20,000 Served. And Counting.

GOLDBELL ENGINEERING PTE LTD

10 Tuas Avenue 18 Singapore 638894

Tel: +65 6861 0007 Fax: +65 6861 3676 (Sales)

Fax : +65 6863 0425 (Service) +65 6862 1347 (Parts)

Website: www.goldbell.com.sg

Co. Reg. No.: 198003963G

(SUPPLEMENTARY)

INSURER: China Taiping Insurance (Singapore) Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:
Policy No:	DMPCSNW00062352100	Date of Loss: 22/09/2021
Vehicle Reg. No.:	SJZ7606B	Driveable?
Driver Age/Info:	/ MALE	Party At Fault: UNKNOWN
TP Injury Involved?	YES	Third Party Involved? YES
Insured/Claimant:	HUSSEIN BIN KAMARUDIN	
Driver:	HUSSAINI HAZIQ BIN HUSSEIN	
Make/Model:	HYUNDAI AVANTE, 1.6 (A)	Vehicle Reg. Date: 24/12/2010
Vehicle Colour:	White	
Engine No:	G4FCAU860428	Chassis No: KMH DU41BMAU033748
Odometer:	0 KM	
Paint Type:		
Total Loss?	NO	
Est. Duration of Repair (day)	14	
Present Location:	GOLDBELL ENGINEERING PTE LTD (TUAS)	

COST OF CLAIMS	Amount
Parts	1,205.00
Miscellaneous Items	0.00
Labour	336.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	1,541.00
+ GST 7.00% (S\$)	107.87
Nett Amount (S\$)	1,648.87
+ Previous Estimates (S\$)	13,800.27
Claim Total (S\$)	15,449.14

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 11 Mar 2022)
Parts:	143	HYUNDAI AVANTE 1.6 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	Goldbell Engineering Pte Ltd/SJZ7606B/11/03/2022 18:22	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount
1	1		*LWR WINDSCREEN COVER	cra	0.00	0.00	*165.00 F
2	1		*INSTRUMENT PNL TRIM	cra	0.00	0.00	*210.00 F
3	1		*AIR INTAKE HOSE	cra	0.00	0.00	*60.00 F
4	1		*AIR INTAKE HOUSING	cra	0.00	0.00	*110.00 F
5	1		*FUSE BOX	cra	0.00	0.00	*580.00 F
6	1		*MODULE BOX HOUSING	cra	0.00	0.00	*80.00 F

F=Franchise part.

Total Parts (S\$) **1,205.00**

Goldbell Engineering Pte Ltd/SJZ7606B/11/03/2022 18:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	L/F WHEELHOUSE REPAIR	New	336.00
Gross Labour Cost (\$\$)			336.00

Goldbell Engineering Pte Ltd/SJZ7606B/11/03/2022 18:22. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

