

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: D17010246MFCV Date: 18th Feb 2022

Our Ref: CS1/FCI22000957/Rvf3e2

M/s Ms First Capital Insurance Ltd

36 Robinson Road #16-01 City House Singapore 068877 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: PA 9349R INSURED VEHICLE: YP 6451L ACCIDENT DATE: 01/11/2017

We thank you for your instruction on 27/01/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of PA 9349R from M/s Crown Asia Bus Builder Pte Ltd.
- b) Singapore Accident Statement of Vehicles PA 9349R and YP 6451L.
- c) Colour damaged vehicle photographs of PA 9349R.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : PA 9349R Make & Model : Isuzu LT134P

Year of Registration : 2010

Chassis Number : JALLT134P97000093

Engine Capacity : 7790 cc

- 2. We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.