



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
SOMPO INSURANCE SINGAPORE PL 50 RAFFLES PLACE #03-03 SINGAPORE LAND TOWERSINGAPORE 048623			Ref: CS/SMO22000962/Uqf3q2	
			Date: 01/04/2022	
			Code: SMO	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	YP 6408M	Veh. Inspected	SMW 2966A
	Policy No.		Coverage (\$)	0.00
	Claim No.	CMTD2200369/SYH	Excess (\$)	0.00
	Assign From	MELVIN YE YONG KANG	Assign Date	27/01/2022
2. Vehicle Particulars & Condition				
	Make & Model	AUDI A8L (A)	c.c	2995
	Engine No.	HIDDEN	Year of Reg.	2016
	Chassis No.	WAUZZZ4H0EN015140	Colour	BLACK
	Odometer	128092 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	255/40Z R20	MICHELIN	7 mm
	L/H Front Tyre	255/40Z R20	MICHELIN	7 mm
	R/H Rear Tyre	255/40Z R20	MICHELIN	7 mm
	L/H Rear Tyre	255/40Z R20	MICHELIN	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE N/S WING MIRROR. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	25/01/2022	Inspection Date	28/01/2022
	Survey held at	TEAM MOTION PTE LTD 61 UBI AVENUE 2,#06-03A,AUTOMOBILE MEGAMART,SINGAPORE 408898		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days	