

1

of 2 ?

100%

▼

Find

Next

LKK

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

64 CECIL STREET

#05-02 IOB BUILDING SINGAPORE 049711

Ref: CS/III22000985/Atf3

Date: 28/01/2022

Code: III2

1. Policy Particulars :- OWN DAMAGE

Insured Veh.	Veh. Inspected	SND 2113H
Policy No. D20MFL0000618-02	Coverage (\$)	0.00
Claim No.	Excess (\$)	0.00
Assign From BHUVANESWARI	Assign Date	28/01/2022

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No. HIDDEN	Year of Reg.	
Chassis No.	Colour	
Odometer -	Steering	
Brakes	Modification	
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	26/01/2022	Inspection Date	28/01/2022
Survey held at	HUA MENG SPRAY PAINTING WORKSHOP 1 KAKI BUKIT AVE 6 #01-61 AUTOBAY SINGAPORE 417883		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.