



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details		
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925		
			Document No. 0				
			Document Date 05/04/2022				
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks
2017	ZVW50R	AHXEBW Q2	23/11/2017	SLU1044P	0	12998	75/DS/SLU1044P
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On
JTDKB3FU503576471		2ZR8258112	60	Ng Mei Yen	28/01/2022 8.00		05/04/2022 18.00
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount	
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:SBS6433X ACC DATE:25/01/2022 DRIVE IN:26/01/2022 DATE-IN: DATE SURVEY:28/01/22 NO OF REPAIR DAYS:4 DAY BY:STEVE LKK				50.00	
2	B	BP-ECU2 TO RESET ECU AND REPROGRAMME				180.00	
3	B	BP-LAB2 TO CHECK WIRING AND LIGHTING. TO WATER TEST FOR LEAK	*			180.00	
4	B	BP-LAB2 R/I REAR REVERSE SENSOR TO FACILIATE REPAIRS AND TST FUNCTION.	*			180.00	
5	B	BP-LAB2 R/I REAR TOP SPOILER AND ATTACHMENT TO FACILIATE REPAIRS.	*			180.00	
6	B	BP-LAB2 TO REPLACE REAR ACCIDENT DAMAGE PARTS. STRAIGHTEN/REALIGN ALL OTHER AFFECTED AREAS.	*			1080.00	
7	B	BP-RES2 TO SPRAY PAINT ON REAR ACCIDENT AFFECTED AREAS.	*			1180.00	
8	1	SPC507-47001 23 BACK SENSOR SILVER METALLIC 1F	1.00	173.10		173.10	
9	2	U81561-47153 LENS & BODY, RR	1.00	469.90		469.90	
10	3	U81591-47011 LENS & BODY, RR	1.00	532.00		532.00	
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total
			Please acknowledge receipt of vehicle		Parts		Less
					Labour		
					Sublet		
					Lubrication/Fluid		Amount Due
					Others		

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept				S1000005 / ICFIC1		M/S Grab Rentals Pte Ltd 6 Battery Road #38-04 Singapore 049909 Work: 65703925			
				Document No. 0					
				Document Date 05/04/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	ZVW50R	AHXEBW Q2	23/11/2017	SLU1044P	0	12998	75/DS/SLU1044P		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDKB3FU503576471		2ZR8258112	60	Ng Mei Yen	28/01/2022	8.00	05/04/2022	18.00	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
11	4	U52159-47913 COVER, RR BUMPER				1.00	469.50		469.50
12	5	U52453-47010 GUARD, RR BUMPER,				1.00	611.30		611.30
13	6	U52161-16010 PIECE, RR BUMPER				1.00	4.80		4.80
14	7	U52023-47030 REINFORCEMENT				1.00	353.10		353.10
15	8	U76085-47916 SPOILER SUB-ASSY, RR				1.00	1668.60		1668.60
16	9	U81006-47030 LAMP SET, STOP CTR				1.00	203.90		203.90
17	0	K52161-0K040 PIECE, RR BUMPER				9.00	4.30		38.70
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 7,554.90		
			Please acknowledge receipt of vehicle		Parts	4,524.90	GST 7.00% 528.84		
					Labour	3,030.00			
					Sublet	0.00	Less 0.00		
					Lubrication/Fluid	0.00			
					Others	0.00	Amount Due 8,083.74		

Customer Copy