

Steve (LKK)
3/2/22, 11:00a

Wor PL
3 dy
PIP, R1 BL sy

SERVICE ESTIMATE

94711 - C00001
Ms Yeo Wei Min Elaine
12 Jalan Emas Urai

SL: SERVICE SALES - PC

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 27/01/2022

WIP No. . : 11160

Veh.In/Out:

*Tel.No. . : Mobile: 93898500

Reg.No. . : SKU9660U

Reg.date . : 25/08/2015

Mileage . : 0

Chassis No: SALLAAAG5GA777650

Singapore 678734

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Ms Yeo Wei Min Elain

Op.No	Description	Mech	Qty	Price	Disc%	Pkg	Amount	G
802	TO REPLACE REAR BUMPER, REAR BUMPER PAD, REAR BUMPER LOWER, REAR REFLECTOR LH, ETC	0	1300	1500.00	0		1,500.00	S
800	TO SPRAY REAR BUMPER	0	1000	1200.00	0		1,200.00	S
280	TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES	0		621.00	0		621.00	S
	BUMPER COVER REAR D4	1.0	EA	2326.60			2,326.60	S
	BUMPER PAD MOULDING	1.0	EA	215.90			215.90	S
	BUMPER MOULDING TOW	1.0	EA	130.00			130.00	S
	BUMPER FOAM REAR DIS	1.0	EA	126.10			126.10	S
	BUMPER RELECTOR REAR	1.0	EA	194.90			194.90	S
	BUMPER RELECTOR REAR	1.0	EA	194.90			194.90	S
	PARKING AID 90 Degre	4.0	EA	367.20			1,468.80	S
	BUMPER BRACKET REAR	1.0	EA	143.50			143.50	S
	BUMPER BRACKET REAR	1.0	EA	143.50			143.50	S
	BUMPER BRACKET REAR	1.0	EA	108.20			108.20	S

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SERVICE ESTIMATE

94711 - C00001 SL: SERVICE SALES - PC

Ms Yeo Wei Min Elaine

12 Jalan Emas Urai

Singapore 678734

Closed by : Juan Paulo Bongon Ba

Svc Consultant :

Remarks : Ms Yeo Wei Min Elain

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 2

Inv.date. : 27/01/2022

WIP No. . : 11160

Veh.In/Out:

*Tel.No. . : Mobile: 93898500

Reg.No. . : SKU9660U

Reg.date . : 25/08/2015

Mileage ... : 0

Chassis No: SALLAAAG5GA777650

Op.No	Description	Mech Qty	Price	Disc%	Pkg	Amount	G
	BUMPER BRACKET REAR <i>7.0 X nn</i>	1.0 EA	108.20			108.20	S
	BUMPER BRACKET REAR <i>7.0 X nn</i>	1.0 EA	139.10			139.10	S
	BUMPER BRACKET REAR <i>7.0 X nn</i>	1.0 EA	126.40			126.40	S
	GRILLE CLIP EVOQUE <i>15.0 EA</i>	15.0 EA	4.00			60.00	S
	BUMPER BRACKET NUT R <i>10.0 EA</i>	10.0 EA	4.10			41.00	S
	LH CTR SENSOR BRACKE <i>1.0 EA</i>	1.0 EA	18.60			18.60	S
	PDC HOLDER REAR LH D <i>1.0 EA</i>	1.0 EA	20.40			20.40	S

Gross Total. 8,887.10

Labour Total 3,321.00
 Parts Total 5,566.10
 Package Total 0.00

Net..... 8,887.10
 GST @ 7.0% 622.10
 Total..... 9,509.20
 Paid..... 0.00
 Please Pay.. 9,509.20

GST: S=StdRated; O=OutOfScope; Z=ZeroRated