



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDINGSINGAPORE 079120 ATTN: LOH CHEE HENG			Ref: CS3/AIG21010221/Rvf3n2-1 Date: 18/02/2022 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	GQ 4359S	Veh. Inspected	GBF 9630S	
Policy No.	1900081072-02	Coverage (\$)	0.00	
Claim No.	6345301349SG	Excess (\$)	0.00	
Assign From	LOH CHEE HENG	Assign Date	28/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	mitsubishi canter fea01	c.c	2998	
Engine No.	HIDDEN	Year of Reg.	2017	
Chassis No.	FEA01BA20519	Colour	WHITE	
Odometer	158673 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/75 R15	BRIDGESTONE	7 mm	
L/H Front Tyre	185/75 R15	BRIDGESTONE	7 mm	
R/H Rear Tyre	155 R12C (D)	BRIDGESTONE	5/5 mm	
L/H Rear Tyre	155 R12C (D)	BRIDGESTONE	5/5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	30/09/2021	Inspection Date	26/10/2021	
Survey held at	ENG SOON PAINTING SVC BLK 4 YEW TEE IND EST 393 - J WOODLANDS ROAD SINGAPORE 677969			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	