



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AIG ASIA PACIFIC INSURANCE PTE LTD 78 SHENTON WAY #09-16 AIG BUILDINGSINGAPORE 079120 ATTN: SALIHA SYED YUSOF			Ref: CS3/AIG21012200/Vtf3n2-1 Date: 23/02/2022 Code: AIG	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLK 7680R	Veh. Inspected	SMN 3174J	
Policy No.	2100499366	Coverage (\$)	0.00	
Claim No.	1076578970SG	Excess (\$)	0.00	
Assign From	SALIHA SYED YUSOF	Assign Date	28/01/2022	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA SIENTA	c.c	1496	
Engine No.	HIDDEN	Year of Reg.	2019	
Chassis No.	MHFZ28H3000064381	Colour	GREY	
Odometer	209871 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	185/60 R15	RAPID	6 mm	
L/H Front Tyre	185/60 R15	RAPID	6 mm	
R/H Rear Tyre	185/60 R15	RAPID	6 mm	
L/H Rear Tyre	185/60 R15	RAPID	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	29/11/2021	Inspection Date	06/12/2021	
Survey held at	PRECISE AUTO SERVICE NO.1 KAKI BUKIT AVE 6 #02-34/36 SINGAPORE 417883			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		5 Working Days		