LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road, #16-00 Springleaf Tower

Our File No: CS/CTI22001005/KTY3E2

Singapore 079909 Date: 29/04/2022

REFERENCE

Insured/Claimant: NG WEI ZHONG, ROYSTON Policy No: DMPCSNW00171382102

Date of Loss: 17/01/2022 Nature of Claim: OD Claim No: SNM22D200579/C01/TANKL

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SMD8063R

Make & Model: VOLKSWAGEN GOLF, 1.4 (A) Engine No: CXS213274

Reg. Date: 08/09/2014 (Man. Year: 2014) Chassis No: WVWZZZAUZFW015241

Colour: Red Odometer: 80704 km

Engine Capacity: 1395 cc
Market Value/New Car Price: \$\$33,000.00

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40ZR18 Rear Tyre Size: 225/40ZR18
Front Left Side: Michelin 8 mm Rear Left Side: Michelin 8 mm
Front Right Side: Michelin 8 mm Rear Right Side: Michelin 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS		Repairer's	Adjuster's	Difference	Diff %
Parts		23,828.00	20,168.00	3,660.00	15.36
Miscellaneous Items		742.00	503.00	239.00	32.21
Labour		1,491.00	1,491.00	0.00	0.00
Paintwork Labour		718.31	718.31	0.00	0.00
Towing		0.00	0.00	0.00	
	Calculated Gross Total (S\$)	26,779.31	22,880.31	3,899.00	14.56
	- Excess (S\$)	0.00	1,000.00	-1,000.00	
	(S\$)	26,779.31	21,880.31	4,899.00	18.29
	+ GST 7.00/0.00% (S\$)	1,874.55	0.00	1,874.55	100.00
	Nett Amount (S\$)	28,653.86	21,880.31	6,773.55	23.64

INSPECTION

Date of Assignment: 28/01/2022 Present Location: S & H Motor Pte Ltd (Sin Ming)

S & H Motor Pte Ltd (Sin Ming)

Date Inspected: 28/01/2022 Inspected At: 160 Sin Ming Drive #07-02, Sin Ming AutoCity

Singapore 575722

Estimated Period of Repair: 11.0 days

Adjuster: KENNETH KONG Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

TOTAL LOSS ASPECT

Market Value: \$33,000.00

OMV: \$20,784.00

PARF Rebate (1): \$3,658.00

Quota Premium Paid: \$60,002.00

COE Rebate (2): \$15,730.00

Total Rebate (1) + (2) =: \$19,388.00

The total amount incurred will be Market Value \$33,000.00 minus Total Rebate \$19,388.00 = \$13,612.00 before excess.

In view of the above, the vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 29 Apr 2022)

Parts: 144 VOLKSWAGEN GOLF 1.4 (A) (Catalogue:Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: (Unsubmitted, no print-code for SMD8063R)

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with

the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Recommended Parts

No. Qty Part No.	Particulars	Condition	Repairer's	Amount
1 1	*Parts		23,828.00 F	*20,168.00 F
F=Franchise part.		Total Parts (S\$)	23,828.00	20,168.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

No (Qty Particulars		Repairer's	Amount
Misce	ellaneous Items			
1 1	1 Misc		742.00	503.00
		Sub Total (S\$)	742.00	503.00
D	and the state of t			

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Pair	ntwork Labour			
1	Labour for paintwork	New	718.31	718.31
<u>Lab</u>	our Items			
2	Labour for panel/mechanical	New	1,491.00	1,491.00
		Gross Labour Cost (S\$)	2,209.31	2,209.31
	Repor	t was unsubmitted during this print-out.		

< END OF ESTIMATES >