

Your Ref : SNM22D200579/C01/TANKL

Date: 29th Apr 2022

Our Ref : CS/CTI22001005/Kty3e2

M/s China Taiping Insurance (S) Pte Ltd

3 Anson Road #16-00

Springleaf Tower

Singapore 079909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SMD 8063R
ACCIDENT ON 17/01/2022**

Instruction was received to inspect the vehicle Reg. No. SMD 8063R. The inspection was conducted on 28/01/2022 at the premises of M/s S & H Motor Pte Ltd, 160 Sin Ming Drive #07-02 Sin Ming Autocity, Singapore 575722.

The following vehicle information was recorded:

| | |
|----------------------|--|
| Registration Number | : SMD 8063R |
| Make/Model | : Volkswagen Golf A7 1.4 TSI AT 5G13GZ W/O HID |
| Year of Registration | : 2014 |
| Body Colour | : Red |
| Chassis Number | : WWZZZZAUZFW015241 |
| Engine Capacity | : 1395 cc |
| Speedometer Reading | : 80704 km |

The vehicle sustained damages at the o/s front portion and undercarriage. The Estimated repair cost of such vehicle is S\$22,880.31 (Sin Dollars: Twenty-Two Thousand Eight Hundred Eighty and Thirty-One cents only.) (Exclude check items S\$2,280.00Nett)
(Details see photographs enclosed)

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

In view of this repair work, we are of the opinion that it would be **uneconomical** to proceed with the repairs and recommend it's to be written off as **"Total Loss"**.

(a) If the vehicle to be "Total Loss"

Market Value

S\$ 33,000.00 (est)

Less: LTA Reimbursement Value (RV)

(S\$ 19,388.00)

S\$ 13,612.00

Less: Excess

(S\$ 1,000.00)

Nett Liability

S\$ 12,612.00

(b) If the vehicle to be "Repair"

Repair Cost (Est)

S\$ 22,880.31

(Exclude check items S\$885.00Nett)

Less: Excess

(S\$ 1,000.00)

Nett Liability

S\$ 21,880.31

(a) – (b) =

(S\$ 9,268.31)

=====

The amount of estimated saving of S\$9,268.31 if the vehicle to be written off as **"Total Loss"** instead of to be repair.

Vehicle Inspected By:



KONG SENG CHEONG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.