

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile |   |                                       |                 |            |                   |  |
|---|---|---------------------------------------|-----------------|------------|-------------------|--|
|   | CHINA TAIPING IN  | ISURANCE (S) PTE LTD                  |                 | Ref:       | CS/CTI22001012/y3 |  |
|   | 3 ANSON ROAD #<br>SPRINGLEAF TOV  |                                       | Date:           | 28/01/2022 |                   |  |
|   |   |                                       |                 | Code:      | СТІ               |  |
| 1.  | . Policy Particulars :- THIRD PARTY CLAIM   |                                       |                 |            |                   |  |
|   | Insured Veh.  | SKV 5279J                             | Veh. Inspected  |            | SKV 3556Y         |  |
|   | Policy No.  | DMPCSNW00051372100                    | Coverage (\$)   |            | 0.00              |  |
|   | Claim No.   | SNM22D200684/C02/SKV5279J<br>/TANKL   | Excess (\$)     |            | 0.00              |  |
|   | Assign From   | TAN KAH LEONG                         | Assign Date     |            | 28/01/2022        |  |
| 2. Vehicle Particulars & Condition                                |   |                                       |                 |            |                   |  |
|   | Make & Model  |                                       | c.c             |            | 0                 |  |
|   | Engine No.  | HIDDEN                                | Year of Reg.    |            |                   |  |
|   | Chassis No.   | Colour                                |                 |            |                   |  |
|   | Odometer  | Steering                              |                 |            |                   |  |
|   | Brakes  |                                       | Modification    |            |                   |  |
|   | General   |                                       |                 |            |                   |  |
| 3. Conditions of Tyres  |   |                                       |                 |            |                   |  |
|   |   | Size                                  | Make            |            | Balance           |  |
|   | R/H Front Tyre  |                                       |                 |            | mm                |  |
|   | L/H Front Tyre  |                                       |                 |            | mm                |  |
|   | R/H Rear Tyre   |                                       |                 |            | mm                |  |
|   | L/H Rear Tyre   |                                       |                 |            | mm                |  |
| 4.  | Description of Damages  |                                       |                 |            |                   |  |
|   |   |                                       |                 |            |                   |  |
| 5.  | General Information   |                                       |                 |            |                   |  |
|   | Accident Date   | 25/01/2022                            | Inspection Date | е          |                   |  |
|   | Survey held at  | SC AUTO INDUSTRIES (S) PTE            | LTD             |            |                   |  |
|   |   | 51, SENOKO ROAD .<br>SINGAPORE 758133 |                 |            |                   |  |
| 5a. Rer   |   |                                       | emarks          |            |                   |  |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |                                       |                 |            |                   |  |